



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**

REGION III
2443 WARRENVILLE ROAD, SUITE 210
LISLE, ILLINOIS 60532-4352

OCT 11 2005

Eric C. Zickgraf, Ph.D.
Radiation Safety Officer
St. Mary Medical Center - Hobart
1500 South Lake Park Avenue
Hobart, IN 46342

Dear Dr. Zickgraf:

Enclosed is Amendment No. 09 to your NRC Material License No. 13-03459-03 in accordance with your request. Please note that the changes made to your license are printed in **bold font**.

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify the U.S. Nuclear Regulatory Commission, Region III office at (630) 829-9887 so that we can provide appropriate corrections and answers.

In accordance with our telephone conversation on September 16, 2005, 10 CFR 35.500 was removed from your NRC license since licensed material was never procured under 35.500 and you have no need for such material. Also certain brachytherapy sources could not be authorized at this time since they do not appear in the Sealed Source and Device Registry (SSDR) as requested in your application for renewal. Specifically, they are, Imagyn Isostar Model IS 12501, Ibt 1251 and Mentor MBI Model 123SH Prostaseed. As we discussed, if in the future you obtain SSDR information regarding these products, you may amend your NRC license to add these sources.


You will be periodically inspected by NRC. Failure to conduct your program in accordance with NRC regulations, license conditions, and representations made in your license application and supplemental correspondence with NRC will result in enforcement action against you. This could include issuance of a notice of violation, or imposition of a civil penalty, or an order suspending, modifying or revoking your license as specified in the General Statement of Policy and Procedure for NRC Enforcement Actions. Since serious consequences to employees and the public can result from failure to comply with NRC requirements, prompt and vigorous enforcement action will be taken when dealing with licensees who do not achieve the necessary meticulous attention to detail and the high standard of compliance which NRC expects of its licensees.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). The NRC's document system is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>. The enclosed license document is exempt from public disclosure in accordance with 10 CFR 2.390, because its disclosure to unauthorized individuals could present a security vulnerability.

E. C. Zickgraf, Ph.D.

2

Sincerely,


James R. Mullauer, M.H.S.
Health Physicist
Materials Licensing Branch

License No. 13-03459-03
Docket No. 030-31379

Enclosure: Amendment No. 09