

18-RES

**From:** Don Marksberry  
**To:** David Loveless  
**Date:** 6/28/04 9:57AM  
**Subject:** S/U transformer soak times

Per Bill, a transformer that has been powered down on the high side (such as a startup transformer) for an hour or two (due to a LOOP) does not need soaking.

Soaking is important for cold transformers, which includes moisture and oil testing in addition to no load soak time.

4/17 K