

NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201		U.S. NUCLEAR REGULATORY COMMISSION	
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
1. LICENSEE/LOCATION INSPECTED: Price William Hospital 8700 Sudley Road Manassas, Virginia 22110		2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
REPORT Nos 2005001			
3. DOCKET NUMBER(S) 030-17771	4. LICENSE NUMBER(S) 45-19485-01	5. DATE(S) OF INSPECTION October 18, 2005	
LICENSEE:  The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:			
<input type="checkbox"/> 1. Based on the inspection findings, no violations were identified.			
<input checked="" type="checkbox"/> 2. Previous violation(s) closed.			
<input type="checkbox"/> 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.			
<input type="checkbox"/> Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):			
          <input checked="" type="checkbox"/> 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.			
Title 10 CFR 20.1906(b), in part, require that each licensee monitor the external surfaces of a package labeled with a Radioactive White I, Yellow II, or Yellow III label for radioactive contamination, unless the package contains only radioactive material in the form of a gas or in special form as defined in 10 CFR 71.4.			
Contrary to the above, the licensee received packages labeled with White I, Yellow II or Yellow III, the packages were not exempt from the monitoring requirement for radioactive contamination, and the licensee did not perform the required monitoring. Specifically, as of October 2005, the wipe test to the radioactive packages received by the licensee were not done.			
This is a Severity Level IV violation (Supplement IV).			
Licensee's Statement of Corrective Actions for Item 4, above.			
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.			
Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	GARY J. HERBEK PRICE WILLIAM HOSPITAL	<i>Gary J. Herbek</i>	10/25/05
NRC INSPECTOR	Shirley Xu	<i>Shirley Xu</i>	10/25/05