



Franklin O. Goforth  
Safety & Environmental Officer  
1075 Everree Inn Road  
Griffin, GA 30224  
770-227-8000 x118 Phone  
404-521-4467 Fax  
frank.goforth@xerium.com

NM583

SEND VIA FAX 610-337-5259 (12 Pages)

January 10, 2006

US NRC

Division of Nuclear Materials Safety  
King of Prussia, Pennsylvania 19406

RE: Weavexx Corporation  
400 Industrial Park Road  
Farmville, VA 23901  
License 45-25180-01 Amendment No. 03

03032615

This manufacturing facility ceased operation in April 2005. We continued to control the facility and radioactive materials as we began moving manufacturing equipment for either disposal or relocation. The named RSO Billy Stanfill continued in this responsibility. I am the RSO for Xerium Technologies, Inc, the parent of Weavexx Corporation. I am also corporate RSO for Weavexx. We have recently completed the transfer of materials for disposal and would like to submit this request for cancellation of the license.

Attached are copies of disposal letter from RAM Services, License 071-1234-01 issued by State of Wisconsin, identifying the sources transferred for disposal. The items are:

Four (4) NDC Model 104 gauges AM-241 Isotope; SN 307 (100 mCi), SN 090 (100 mCi), SN 1835 (150 mCi), SN 039 (100 mCi).

Three (3) Ohmart Model BAL gauges KR-85 Isotope; SN 3127 (65 mCi), SN 8255 (1200 mCi), SN 3120 (65 mCi).

Two (2) sources were transferred to our Manufacturing location in Starkville MS, under license MS 745-01. I am the named RSO for that license also. The materials are received and placed in secure storage location.

NDC Model 104 SN 3446 (150 mCi), SN 3443 (150 mCi). Attached are copies of leak test conducted in June of 2005.

We have no records of incidents that would have resulted in contamination of this facility. We are the current owner and the site is available for inspection if necessary.

138218

NUCLEAR MATERIALS-002

Please review the information provided and advise if you require anything further.

Regards,

  
Franklin O. Goforth  
Safety & Environmental Officer, RSO

Enclosures

RAM Services Certificate of Disposal

Leak Test Certificates for Disposed Sources

Delivery Receipts for Disposed Sources

Leak Test Certificates for Transferred Sources

Letters of Assignment as RSO for Xerium Technologies, Inc. and Weavexx Corporation

cc. RSO Files



510 COUNTY HIGHWAY V  
TWO RIVERS, WI 54241  
VOICE: +1-920-686-3889  
FAX: +1-920-686-3899

06 January 2006

Mr. Frank Goforth  
Xerium Technologies  
Stowe Woodward Corp.  
1075 Everee Inn Road  
Griffin, GA 30223

In Re: Disposal of radioactive gauges

Dear Mr. Goforth,

We are hereby informing you that as of this date we have received the radioactive gauges listed below that were shipped from your Farmville, VA facility via FedEx under airwaybills 855577711363 and 855577711374 and that we have taken possession of them under our State of Wisconsin radioactive material license for recycling or disposal of the radioactive materials.

Manufacturer	Model	S/N	Isotope	Activity	Activity Date
NDC	104	307	Am-241	100 mCi	07/1976
NDC	104	090	Am-241	100 mCi	08/1972
NDC	104	1835	Am-241	150 mCi	08/1988
NDC	104	039	Am-241	100 mCi	1971
Ohmart	BAL	3127	Kr-85	65 mCi	07/1988
Ohmart	BAL	8255	Kr-85	1200 mCi	11/1982
Ohmart	BAL	3120	Kr-85	65 mCi	12/1984

Upon opening the drums, the NDC gauges were tested for leakage and all 4 devices passed. The Ohmart gauges containing Kr-85 do not require leak testing.

Please retain these records as required by the terms of your license or regulations for decommissioning and license termination.

Please contact us if you require additional information or assistance.

Sincerely,

A handwritten signature in cursive script, appearing to read "Jerry P. Wiza".

Jerry P Wiza, President  
Enc.



## STATE OF WISCONSIN RADIOACTIVE MATERIALS LICENSE 071-1234-01

SEALED SOURCE LEAK TEST CERTIFICATE			
RAM ACCESSION NO.		39019	
GENERAL CERTIFICATE			
LOCATION			
CONTACT PERSON		TELEPHONE	
RAM Services, Inc.			
LEAK TEST ANALYSIS			
SOURCE MODEL	104	DEVICE/TOOL NUMBER	
SOURCE SERIAL NO.	039	MANUFACTURER S/N	
ISOTOPE	AM-241	SOURCE ORIGINAL ACTIVITY	100.0000 mCi 3.7000 GBq
DATE SOURCE WPED	06 Jan 2006	REASON FOR TEST	DISPOSAL
ANALYSIS DATE	06 Jan 2006	ANALYTICAL METHOD	Liquid Scintillation Counting
RAW SAMPLE COUNT	29.9754 cpm	INSTRUMENT	Beckman LS 6500 706-9054
BACKGROUND	29.00000 cpm	COUNTING EFFICIENCY	95.00%
NET SAMPLE COUNT	0.975368 cpm	MINIMUM DETECTABLE ACTIVITY	1.33E-05 $\mu$ CI 0.49 Bq
SAMPLE ANALYSIS ACTIVITY	0.439E-06 $\mu$ CI 0.016 Bq	PASS/FAIL CRITERION	0.005 $\mu$ CI 185 Bq
SOURCE PASSES TEST		ACTION LEVEL	0.001 $\mu$ CI 37 Bq
ANALYST Don Jordan			
NOTES: [XERUM // WEAVEXX ] [ ] [FARMVILLE] LEAK TESTED UPON RECEIPT FROM FARMVILLE			

PRINTED IN THE UNITED STATES OF AMERICA

510 COUNTY HIGHWAY V ▲ TWO RIVERS, WISCONSIN 54241 ▲ VOICE: +1.920.686.3889 FAX: 1.920.686.3899



STATE OF WISCONSIN RADIOACTIVE MATERIALS LICENSE 071-1234-01

SEALED SOURCE LEAK TEST CERTIFICATE			
RAM ACCESSION NO		39018	
GENERAL CERTIFICATE			
LOCATION			
CONTACT PERSON		TELEPHONE	
RAM Services, Inc.			
LEAK TEST ANALYSIS			
SOURCE MODEL	104	DEVICE/TOOL NUMBER	
SOURCE SERIAL NO	090	MANUFACTURER S/N	
ISOTOPE	AM-241	SOURCE ORIGINAL ACTIVITY	100.0000 mCi 3.7000 GBq
DATE SOURCE WIPED	06 Jan 2006	REASON FOR TEST	DISPOSAL
ANALYSIS DATE	06 Jan 2006	ANALYTICAL METHOD	Liquid Scintillation Counting
RAW SAMPLE COUNT	30.032 cpm	INSTRUMENT	Beckman LS 6500 706-9054
BACKGROUND	34.00000 cpm	COUNTING EFFICIENCY	95.00%
NET SAMPLE COUNT	-3.968 cpm	MINIMUM DETECTABLE ACTIVITY	1.43E-05 µCi 0.53 Bq
SAMPLE ANALYSIS ACTIVITY	0.000 µCi 0.000 Bq	PASS/FAIL CRITERION	0.005 µCi 185 Bq
SOURCE PASSES TEST		ACTION LEVEL	0.001 µCi 37 Bq
ANALYST	Don Jordan		
NOTES	[XERIUM / WEAVEXX] II [FARMVILLE] LEAK TESTED UPON RECEIPT FROM FARMVILLE		

PRINTED IN THE UNITED STATES OF AMERICA

510 COUNTY HIGHWAY V ▲ TWO RIVERS, WISCONSIN 54241 ▲ VOICE: +1.920.686.3889 FAX: 1.920.686.3899



## STATE OF WISCONSIN RADIOACTIVE MATERIALS LICENSE 071-1234-01

SEALED SOURCE LEAK TEST CERTIFICATE			
RAM ACCESSION NO.		39017	
GENERAL CERTIFICATE			
LOCATION			
CONTACT PERSON		TELEPHONE	
RAM Services, Inc.			
LEAK TEST ANALYSIS			
SOURCE MODEL	104	DEVICE/TOOL NUMBER	
SOURCE SERIAL NO.	1835	MANUFACTURER S/N	
ISOTOPE	AM-241	SOURCE ORIGINAL ACTIVITY	150.0000 mCi 5.5500 GBq
DATE SOURCE WPED	06 Jan 2006	REASON FOR TEST	DISPOSAL
ANALYSIS DATE	06 Jan 2006	ANALYTICAL METHOD	Liquid Scintillation Counting
RAW SAMPLE COUNT	46 2741 cpm	INSTRUMENT	Bockman LS 6500 706-9054
BACKGROUND	34.00000 cpm	COUNTING EFFICIENCY	95.00%
NET SAMPLE COUNT	12 2741 cpm	MINIMUM DETECTABLE ACTIVITY	1.43E-05 $\mu$ CI 0.53 Bq
SAMPLE ANALYSIS ACTIVITY	5.529E-06 $\mu$ CI 0.205 Bq	PASS/FAIL CRITERION	0.005 $\mu$ CI 1.85 Bq
SOURCE PASSES TEST		ACTION LEVEL	0.001 $\mu$ CI 37 Bq
ANALYST Don Jordan			
NOTES: [XERIUM // WEAVEXX ] [ (FARMVILLE) LEAK TESTED UPON RECEIPT FROM FARMVILLE			

PRINTED IN THE UNITED STATES OF AMERICA

510 COUNTY HIGHWAY V ▲ TWO RIVERS, WISCONSIN 54241 ▲ VOICE: +1. 920.686.3889 FAX: 1.920.686.3899



STATE OF WISCONSIN RADIOACTIVE MATERIALS LICENSE 071-1234-01

SEALED SOURCE LEAK TEST CERTIFICATE			
RAM ACCESSION NO.		39016	
GENERAL CERTIFICATE			
LOCATION			
CONTACT PERSON		TELEPHONE	
RAM Services, Inc.			
LEAK TEST ANALYSIS			
SOURCE MODEL	104	DEVICE/TOOL NUMBER	
SOURCE SERIAL NO.	307	MANUFACTURER S/N	
ISOTOPE	AM-241	SOURCE ORIGINAL ACTIVITY	100.0000 mCi 3.7000 GBq
DATE SOURCE WIPED	06 Jan 2006	REASON FOR TEST	DISPOSAL
ANALYSIS DATE	06 Jan 2006	ANALYTICAL METHOD	Liquid Scintillation Counting
RAW SAMPLE COUNT	43.4232 cpm	INSTRUMENT	Beckman LS 6500 706-9054
BACKGROUND	34.00000 cpm	COUNTING EFFICIENCY	95.00%
NET SAMPLE COUNT	9.42316 cpm	MINIMUM DETECTABLE ACTIVITY	1.43E-05 $\mu$ CI 0.53 Bq
SAMPLE ANALYSIS ACTIVITY	4.245E-06 $\mu$ CI 0.157 Bq	PASS/FAIL CRITERION	0.005 $\mu$ CI 185 Bq
SOURCE PASSES TEST		ACTION LEVEL	0.001 $\mu$ CI 37 Bq
ANALYST	Don Jordan		
NOTES:	[XERUM // WEAVEXX ] [FARMVILLE] LEAK TEST DONE UPON RECEIPT FROM FARMVILLE		

PRINTED IN THE UNITED STATES OF AMERICA

510 COUNTY HIGHWAY V ▲ TWO RIVERS, WISCONSIN 54241 ▲ VOICE: +1.920.686.3889 FAX: 1.920.686.3899



FedEx Express  
Customer Support Trace  
3875 Airways Boulevard  
Module H, 4th Floor  
Memphis, TN 38116

U.S. Mail: PO Box 727  
Memphis, TN 38194-4643  
Telephone: 901-369-3600

01/06/2006

Dear Customer:

The following is the proof of delivery you requested with the tracking number **855577711363**.

---

**Delivery Information:**

---

<b>Status:</b>	Delivered	<b>Delivery date:</b>	Jan 6, 2006 10:08
<b>Signed for by:</b>	B.MEYER		
<b>Service type:</b>	Priority Overnight		

**NO SIGNATURE IS AVAILABLE**

FedEx Express Proof of delivery details appear below; however no signature is currently available for this FedEx Express shipment. Availability of signature images may take up to 5 days after delivery date.

---

**Shipping Information:**

---

<b>Tracking number:</b>	855577711363	<b>Ship date:</b>	Jan 5, 2006
<b>Recipient:</b>	TWO RIVERS, WI US	<b>Shipper:</b>	GRIFFIN, GA US
<b>Reference</b>			UH 2911

Thank you for choosing FedEx Express.

FedEx Worldwide Customer Service  
1.800.GoFedEx 1.800.463.3339





FedEx Express  
Customer Support Trace  
3875 Airways Boulevard  
Module H, 4th Floor  
Memphis, TN 38116

U.S. Mail: PO Box 727  
Memphis, TN 38194-4643  
Telephone: 901-369-3600

01/06/2006

Dear Customer:

The following is the proof of delivery you requested with the tracking number **855577711374**.

---

**Delivery Information:**

---

<b>Status:</b>	Delivered	<b>Delivery date:</b>	Jan 6, 2006 10:08
<b>Signed for by:</b>	B.MEYER		
<b>Service type:</b>	Priority Overnight		

**NO SIGNATURE IS AVAILABLE**

FedEx Express Proof of delivery details appear below however no signature is currently available for this FedEx Express shipment. Availability of signature images may take up to 5 days after delivery date

---

**Shipping Information:**

---

<b>Tracking number:</b>	855577711374	<b>Ship date:</b>	Jan 5, 2006
<b>Recipient:</b>	TWO RIVERS, WI US	<b>Shipper:</b>	GRIFFIN, GA US
<b>Reference</b>			UN 2911

Thank you for choosing FedEx Express.

FedEx Worldwide Customer Service  
1.800.GoFedEx 1.800.463.3339



Global Dosimetry

2652 McGaw Avenue Irvine, CA 92614 Tel: (949) 419-1000 Toll Free: (888) 437-1714 Fax: (949) 296-1144 www.dosimetry.com


Customer: 90395L  
Location ID 00000DPT  
Report Number: 1485

Sealed Radioactive Source Leak Test Certificate  
Save this report for your records

Weavexx  
Billy Stanfill  
1504 Lee Drive  
Farmville, VA 23901

Isotope	Activity/ Date	Source Manufacturer:	Collected By:	Analyzed By:	Result (uCi)
Am-241	150 mCi	NDC Model: 103 Serial: 3446	Billy Stanfill Collected On: 6/2/2005 Using GDS Q1 ki	GDS Counting Lab Analyzed On: 06/09/2005	0.0000
Am-241	150 mCi	NDC Model: 103 Serial: 3443	Billy Stanfill Collected On: 6/2/2005 Using GDS Q1 ki	GDS Counting Lab Analyzed On: 06/09/2005	0.0000

The Leak Tests were analyzed in accordance with Global Dosimetry Solutions, Inc. procedures and Radioactive Material License #4635-30. Calibration and Quality Control records are maintained for the Leak Test Counting Equipment at Global Dosimetry Solutions, Inc.

  
Radiation Safety Officer Review

6/17/2005  
Date



August 5, 2004

To US Nuclear Regulatory Agency, State Radiation Program Agencies and other interested parties

Subject: Assignment as Radiation Safety Officer, Xerium, Inc.

As Vice President and Chief Financial Officer of Xerium, Inc., I have delegated authority for all matters pertaining to our Radioactive Materials Program to Franklin O. Goforth. Franklin O. Goforth has management approval to sign and submit requests on behalf of Xerium, Inc. I understand that license renewals may require the signature of a representative from upper management. This authorization shall remain in effect until revoked in writing.

A handwritten signature in dark ink, reading "Michael P. O'Donnell". The signature is fluid and cursive, with the first and last names being more prominent.

Michael P. O'Donnell  
VP and Chief Financial Officer



August 5, 2004

To US Nuclear Regulatory Agency, State Radiation Program Agencies and other interested parties

Subject: Assignment as Radiation Safety Officer, Weavexx Corporation.

As Controller of Weavexx Corporation, I have delegated authority for all matters pertaining to our Radioactive Materials Program to Franklin O. Goforth. Franklin O. Goforth has management approval to sign and submit requests on behalf of Weavexx Corporation. I understand that license renewals may require the signature of a representative from upper management. This authorization shall remain in effect until revoked in writing.

A handwritten signature in cursive script that reads 'Kathleen T. Stuart'.

Kathleen T. Stuart  
Controller  
Weavexx Corporation

This is to acknowledge the receipt of your letter/application dated

1/10/2006, and to inform you that the initial processing which includes an administrative review has been performed.

☒ TEAM 45-25180-01  
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

☐ Please provide to this office within 30 days of your receipt of this card

---

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 133218.  
When calling to inquire about this action, please refer to this control number.  
You may call us on (610) 337-5398, or 337-5260.