



DEPARTMENT OF THE NAVY
NAVAL SEA SYSTEMS COMMAND DETACHMENT
RADIOLOGICAL AFFAIRS SUPPORT OFFICE (RASO)
NWS P.O. DRAWER 260
YORKTOWN, VA 23691-0260

2:23

45-23645-01NA
03029462/2005001

5104/67004
Ser 02A/06-0005/020
19 January 2006

From: Officer in Charge, Naval Sea Systems Command Detachment,
Radiological Affairs Support Office (RASO)
To: Commanding General, Marine Corps Logistics Command, Albany
Subj: RADIOLOGICAL AFFAIRS SUPPORT PROGRAM (RASP) INSPECTIONS OF
MARINE CORPS LOGISTICS COMMAND, ALBANY ON 24-28 JANUARY
2005 AND 18-20 OCTOBER 2005
Ref: (a) NRSC ltr 5104 Ser N455C/N45U9011243 of 4 Mar 05
(b) NRSC ltr 5104 Ser N455C/N5U9011484 of 8 Nov 05
(c) CG MARCORLOGCOM ltr 5104 L11/L14 of 22 Dec 05

1. On 24-28 January 2005, the Naval Sea Systems Command Detachment, Radiological Affairs Support Office (NAVSEADET RASO) conducted an inspection of radioactive commodities operations authorized by Naval Radioactive Materials Permit (NRMP) No. 10-67004-T1NP at Marine Corps Logistics Command (MARCORLOGCOM), Albany, Georgia. A formal report of the inspection, reference (a), was issued by the Chairman of the Naval Radiation Safety Committee (NRSC) (Chief of Naval Operations (N455)). The same operations were re-inspected on 18-20 October 2005. Reference (b) is the formal report issued by the NRSC for the re-inspection. Both references (a) and (b) assigned an unsatisfactory rating to MARCORLOGCOM.
2. Reference (a) required command responses within 30 days from the date of the inspection reports with progress reports required every 30 days until all findings are adequately corrected. Reference (b) stated that responses to the re-inspection could be incorporated into the progress reports required by reference (a).
3. The latest progress report on implementation of corrective actions in response to references (a) and (b), reference (c), has been reviewed and is considered satisfactory to correct program deficiencies once implemented. The following information is provided as an update to clarify the status of responses to references (a) and (b):
 - a. Further actions to closeout Immediate Actions 1 and 2 are not feasible, therefore Immediate Actions 1 and 2 are considered closed and require no further response.

NMSS/RGNI MATERIALS-004

Subj: RADIOLOGICAL AFFAIRS SUPPORT PROGRAM (RASP) INSPECTIONS
OF MARINE CORPS LOGISTICS COMMAND, ALBANY ON
24-28 JANUARY 2005 AND 18-20 OCTOBER 2005

b. Reference (a) Findings A.7, E.9, I.2, and I.3 remain open and require updates in future progress reports.

c. Reference (b) Findings A.1 and I.1 were adequately addressed and corrective actions taken deemed appropriate. These items are considered closed.

d. Reference (b) Findings A.7, E.7, E.7, F.37 and F.45 have been reviewed and proposed actions to correct deficiencies are considered to be satisfactory. These findings remain open and require updates in future progress reports until implementation is complete.

4. NAVSEADET RASO recognizes the significant improvements made towards correcting the outstanding findings and the need for reducing the administrative burden to allow implementation of the remaining corrective actions. Therefore, the requirement for submission of progress reports for the remaining open findings of references (a) and (b) has been extended to 60 days. The next progress report is due on 1 March 2006 with subsequent reports required at 60-day intervals until all corrective actions are complete. The progress report shall be submitted to Officer in Charge, NAVSEADET RASO, NWS P.O. Drawer 260, Yorktown, VA, 23691-0260, with copies to COMNAVSEASYSOM (SEA 04N) and CNO N455.

5. For further information, contact Timothy P. Hart at NAVSEADET RASO by e-mail at harttp@raso.navy.mil or by telephone at DSN 953-4692, commercial (757) 887-4692 or commercial fax (757) 887-3235.


J. P. ALDRIDGE

Copy to:
CNO (N455)
COMNAVSEASYSOM (SEA 04N)
CMC (SD)
NRC Region I