



FPL Energy
Seabrook Station

FPL Energy Seabrook Station
P.O. Box 300
Seabrook, NH 03874
(603) 773-7000

January 23, 2006

Docket No. 50-443

SBK-L- 06014

U.S. Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, DC 20555-0001

Seabrook Station
2005 Annual Report of Removable
Contamination from Sealed Source or Fission Detector

In accordance with Technical Specification 3.7.8, "Sealed Source Contamination," FPL Energy Seabrook, LLC hereby reports that during 2005, there were no leaking sources.

Should you have any questions, please contact Mr. Ronald M. Thurlow, Acting Health Physics Department Manager, at (603) 773-7438.

Very truly yours,

FPL Energy Seabrook, LLC

Gene St. Pierre
Site Vice President

cc: S. J. Collins, NRC Region I Administrator
G. E. Miller, NRC Project Manager
G. T. Dentel, NRC Resident Inspector

A0011