

February 18, 2006

Mr. John S. Keenan
Senior Vice President – Generation
and Chief Nuclear Officer
Pacific Gas and Electric Company
Diablo Canyon Power Plant
P.O. Box 770000, Mail Code B32
San Francisco, CA 94177-0001

SUBJECT: DIABLO CANYON POWER PLANT, UNIT NO. 2 - REVIEW OF STEAM
GENERATOR TUBE INSPECTION REPORTS FOR THE 2004 OUTAGE
(TAC NO. MC9301)

Dear Mr. Keenan:

By letters dated November 30, 2004, March 16, and August 25, 2005 (Agencywide Documents Access and Management System (ADAMS) Accession Nos. ML043430465, ML050820052, and ML052440285, respectively), Pacific Gas and Electric Company, the licensee for Diablo Canyon Power Plant (DCPP), Unit No. 2, submitted reports summarizing several aspects of the steam generator tube inspections performed at DCPP, Unit No. 2, during their 2004 twelfth refueling outage (2R12). Additional information concerning the 2004 steam generator tube inspections at DCPP, Unit No. 2, was summarized by the Nuclear Regulatory Commission (NRC) staff in a letter dated January 4, 2005 (ADAMS Accession No. ML043570323). The NRC staff's review of these reports is documented in letter dated October 25, 2005 (ADAMS Accession No. ML052860374).

By letter dated December 16, 2005 (ADAMS Accession No. ML053560067), the licensee provided additional information regarding the 2004 outage (2R12) at DCPP, Unit No. 2, to satisfy the requirements of Technical Specification 5.6.10.b. The NRC staff reviewed this submittal and concludes that the licensee provided the information required by its technical specifications. In addition, the NRC staff did not identify any issues that were not previously addressed in the review dated October 25, 2005.

If you have any questions regarding this matter, please contact me at (301) 415-1445.

Sincerely,

/RA/

Alan B. Wang, Project Manager
Plant Licensing Branch IV
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-323

cc: See next page

February 18, 2006

Mr. John S. Keenan
Senior Vice President – Generation
and Chief Nuclear Officer
Pacific Gas and Electric Company
Diablo Canyon Power Plant
P.O. Box 770000, Mail Code B32
San Francisco, CA 94177-0001

SUBJECT: DIABLO CANYON POWER PLANT, UNIT NO. 2 - REVIEW OF STEAM
GENERATOR TUBE INSPECTION REPORTS FOR THE 2004 OUTAGE
(TAC NO. MC9301)

Dear Mr. Keenan:

By letters dated November 30, 2004, March 16, and August 25, 2005 (Agencywide Documents Access and Management System (ADAMS) Accession Nos. ML043430465, ML050820052, and ML052440285, respectively), Pacific Gas and Electric Company, the licensee for Diablo Canyon Power Plant (DCPP), Unit No. 2, submitted reports summarizing several aspects of the steam generator tube inspections performed at DCPP, Unit No. 2, during their 2004 twelfth refueling outage (2R12). Additional information concerning the 2004 steam generator tube inspections at DCPP, Unit No. 2, was summarized by the Nuclear Regulatory Commission (NRC) staff in a letter dated January 4, 2005 (ADAMS Accession No. ML043570323). The NRC staff's review of these reports is documented in letter dated October 25, 2005 (ADAMS Accession No. ML052860374).

By letter dated December 16, 2005 (ADAMS Accession No. ML053560067), the licensee provided additional information regarding the 2004 outage (2R12) at DCPP, Unit No. 2, to satisfy the requirements of Technical Specification 5.6.10.b. The NRC staff reviewed this submittal and concludes that the licensee provided the information required by its technical specifications. In addition, the NRC staff did not identify any issues that were not previously addressed in the review dated October 25, 2005.

If you have any questions regarding this matter, please contact me at (301) 415-1445.

Sincerely,

/RA/

Alan B. Wang, Project Manager
Plant Licensing Branch IV
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-323

cc: See next page

DISTRIBUTION:

PUBLIC

RidsNrrDorl (CHaney/CHolden)

RidsAcrsAcnwMailCenter

RidsOgcRp

LLund

LPLIV Reading

RidsNrrLALFeizollahi

RidsRegion4MailCenter (BJones)

KKarwoski

MMurphy

RidsNrrPMAWang

RidsNrrDorlLplg (DTerao)

ACCESSION NO.: **ML060400176**

NRR-106

*Memo dated

OFFICE	LPL4/PM	LPL4/LA	CSGB/BC	LPL4/BC
NAME	AWang	LFeizollahi	AHiser	DTerao
DATE	02/15/06	02/15/06	1/13/06	02/18/06

DOCUMENT NAME: E:\Filenet\ML060400176.wpd

OFFICIAL RECORD COPY

Diablo Canyon Power Plant, Units 1 and 2

cc:

NRC Resident Inspector
Diablo Canyon Power Plant
c/o U.S. Nuclear Regulatory Commission
P.O. Box 369
Avila Beach, CA 93424

Sierra Club San Lucia Chapter
ATTN: Andrew Christie
P.O. Box 15755
San Luis Obispo, CA 93406

Ms. Nancy Culver
San Luis Obispo
Mothers for Peace
P.O. Box 164
Pismo Beach, CA 93448

Chairman
San Luis Obispo County Board of
Supervisors
Room 370
County Government Center
San Luis Obispo, CA 93408

Mr. Truman Burns
Mr. Robert Kinosian
California Public Utilities Commission
505 Van Ness, Room 4102
San Francisco, CA 94102

Diablo Canyon Independent Safety
Committee
ATTN: Robert R. Wellington, Esq.
Legal Counsel
857 Cass Street, Suite D
Monterey, CA 93940

Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
Harris Tower & Pavillion
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

Richard F. Locke, Esq.
Pacific Gas & Electric Company
P.O. Box 7442
San Francisco, CA 94120

City Editor
The Tribune
3825 South Higuera Street
P.O. Box 112
San Luis Obispo, CA 93406-0112

Mr. Ed Bailey, Chief
Radiologic Health Branch
State Department of Health Services
P.O. Box 997414 (MS 7610)
Sacramento, CA 95899-7414

Mr. James D. Boyd, Commissioner
California Energy Commission
1516 Ninth Street (MS 31)
Sacramento, CA 95814

Mr. James R. Becker, Vice President
Diablo Canyon Operations
and Station Director
Diablo Canyon Power Plant
P.O. Box 3
Avila Beach, CA 93424

Jennifer Tang
Field Representative
United States Senator Barbara Boxer
1700 Montgomery Street, Suite 240
San Francisco, CA 94111

February 2006