

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Abonmarche Consultants, Inc.
95 West Main Street
Benton Harbor, MI

2. NRC/REGIONAL OFFICE

REGION III
US NUCLEAR REGULATORY COMMISSION
2443 WARRENVILLE ROAD, SUITE 210
LISLE, ILLINOIS 60532

REPORT

2006-001

3. DOCKET NUMBER(S)

03033895

4. LICENSEE NUMBER(S)

21-26663-01

5. DATE(S) OF INSPECTION

2/24/06

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):


- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Ed Kulzer	E. L. Kulzer	2/24/06

Docket File Information
**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**



1. LICENSEE Abonmarche Consultants, Inc.		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-33895		4. LICENSE NUMBER(S) 21-26663-01	5. DATE(S) OF INSPECTION February 24, 2006
6. INSPECTION PROCEDURES USED 87124		7. INSPECTION FOCUS AREAS 03.01 - 03.07	
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM 03121	2. PRIORITY 5	3. LICENSEE CONTACT Kenton Mc Andrew	4. TELEPHONE NUMBER 616/927-2295
<input checked="" type="checkbox"/> Main Office Inspection Next Inspection Date: February 2006 / (
<input type="checkbox"/> Field _____			
<input type="checkbox"/> Temporary Job Site _____			

PROGRAM SCOPE

The licensee is an engineering firm that employs approximately 60 individuals at this facility. The licensee possesses three Troxler Model 3440 series moisture density gauges, for use daily/weekly during the construction season (May-November) for DOT road and other construction projects. The licensee does not perform any service or maintenance activities on its gauges; these services are performed by the manufacturer. Currently, the licensee employs five authorized gauge users who have completed manufacturers' training. Two of the devices were stored in a vault in the licensee's office in Benton Harbor, Michigan. The third device was located in Manistee, Michigan.

Performance Observations

At the time of this inspection, the gauges were not in use. The licensee possessed required shipping papers which contained all appropriate information. Gauges/cases were locked in the storage room which was also locked and labeled. The gauges had not been used for the past six months. The inspector performed independent and confirmatory radiation measurements which indicated similar results as noted in the licensee's survey records.