

<b>U.S. NUCLEAR REGULATORY COMMISSION</b>		Date: 03/13/06
<b>TELEPHONE CONVERSATION RECORD</b>		Time: 0900
Mail Control	2006001	License No(s). 29-30922-01
or Report No(s).		Docket No(s). 03036601
<p>Name of Licensee: East Brunswick Surgery Center, LLC d/b/a Robert Wood Johnson Surgery Center</p> <p>Name of Participant(s): Christine Reilly, Administrator</p> <p>Telephone No. 732-390-4300</p> <p>Subject: Phone Inspection Performed 3/13/06 (NOTE: This will be used as the Documents Title in ADAMS)</p>		
<p>Summary:</p> <p>Spoke with Ms. Reilly regarding the license for 35.400 activities that was issued to East Brunswick Surgery Center, LLC (EBSC) on July 20, 2004. Ms. Reilly stated that no procedures have been performed using licensed material and that none were currently scheduled. The surgery center has only performed one brachytherapy procedure since opening. The nuclide used for the procedure was Pd-103.</p> <p>I informed Ms. Reilly that EBSC must contact the NRC once licensed activities begin. Ms. Reilly stated that she would contact the NRC prior to performing licensed activities.</p> <p>This telephone record will serve as documentation of the phone inspection that was performed.</p>		
<p>Action Required: Update next required inspection date to 3/2007.</p>		
<p>Document Availability: <input checked="" type="checkbox"/> Publicly Available <input type="checkbox"/> Non-Publicly Available</p> <p><input checked="" type="checkbox"/> Non-Sensitive <input type="checkbox"/> Non-Sensitive Copyright <input type="checkbox"/> Sensitive <input type="checkbox"/> Sensitive Copyright</p> <p><input type="checkbox"/> Immediate Release <input checked="" type="checkbox"/> Normal Release <input type="checkbox"/> Delay Release Date</p> <p>Prepared &amp; SISP Review Completed By: / RA / CHott Date: 3/13/06</p>		