



UNITED STATES  
**NUCLEAR REGULATORY COMMISSION**  
REGION I  
475 ALLENDALE ROAD  
KING OF PRUSSIA, PENNSYLVANIA 19406-1415

March 15, 2006

Docket No. 03035377

License No. 45-25516-01

Martin A. Hellkamp  
President  
Odyssey Imaging, LLC  
315 Hospital Drive, Suite 205  
Martinsville, VA 24112

SUBJECT: INSPECTION 03035377/2006001, ODYSSEY IMAGING, LLC, MARTINSVILLE, DANVILLE, CHRISTIANSBURG, SOUTH BOSTON AND SALEM, VIRGINIA SITES

Dear Mr. Hellkamp:

This letter forwards NRC Form 591, "Safety Inspection," indicating that no items of non-compliance were found during the inspection of your licensed activities. Please retain the form in your files. No acknowledgment of this letter is required. However, should you have any questions, we shall be pleased to discuss them with you.

The inspector did have a minor concern involving radioactive material contamination at your Christiansburg, Virginia location. This concern was discussed during a telephone conversation with your Radiation Safety Officer, Mr. Charles Anthony Giomuso, on March 10, 2006. In response to our concern, Mr. Giomuso acted immediately to have the technologist who worked at the Christiansburg facility spend the day improving her contamination control techniques with a senior technologist at another of your facilities. In the Christiansburg facility, the inspector also noted that doors leading from the hot lab to a file storage room and a water heater room had locks installed backwards so that individuals were prevented from entering the file room and water heater room from the hot lab instead of the reverse. While this situation did not constitute a security problem, the Nuclear Medicine Technologist at the Christiansburg facility committed to installing the locks in the proper manner. NRC will review these actions during a future inspection of your licensed program.

Current NRC regulations are included on the NRC's website at [www.nrc.gov](http://www.nrc.gov); select **Nuclear Materials; Medical, Industrial, and Academic Uses of Nuclear Material**; then **Toolkit Index Page**. The current Enforcement Policy is included on the NRC's website at [www.nrc.gov](http://www.nrc.gov); select **What We Do, Enforcement**, then **Enforcement Policy**. Or you may obtain these documents by contacting the Government Printing Office (GPO) toll-free at 1-888-293-6498. The GPO is open from 7:00 a.m. to 9:00 p.m. EST, Monday through Friday (except Federal holidays).

M. Hellkamp  
Odyssey Imaging, LLC

2

Your cooperation with us is appreciated.

Sincerely,

***Original signed by James P. Dwyer***

James P. Dwyer, Chief  
Commercial and R&D Branch  
Division of Nuclear Materials Safety

Enclosure:  
NRC Form 591

cc:  
Charles A. Giomuso, Radiation Safety Officer

M. Hellkamp  
Odyssey Imaging, LLC

3

DOCUMENT NAME: E:\Filenet\ML060800248.wpd

**SISP Review Complete: DLawyer**

After declaring this document "An Official Agency Record" it will be released to the Public.

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/ attach/encl "N" = No copy

OFFICE	DNMS/RI	N	DNMS/RI	N	DNMS/RI			
NAME	DLawyer		JDwyer					
DATE	03/15/2006		3/15/2006					

OFFICIAL RECORD COPY