

March 22, 2006

Mr. Christopher M. Crane
President and Chief Nuclear Officer
Exelon Nuclear
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

SUBJECT: ERRATA TO DRESDEN NUCLEAR POWER STATION, UNITS 2 AND 3
NRC PROBLEM IDENTIFICATION AND RESOLUTION INSPECTION
REPORT 05000237/2006002; 05000249/2006002

Dear Mr. Crane:

On March 9, 2006, the U.S. Nuclear Regulatory Commission (NRC) issued problem identification and resolution Inspection Report 05000237/2006002; 05000249/2006002 (ML060680422) for your Dresden Nuclear Power Station, Units 2 and 3. The list of items opened and closed during the inspection is incomplete in the original report. The enclosed errata contains the complete listing, and should be inserted where appropriate into problem identification and resolution Inspection Report 05000237/2006002; 05000249/2006002.

We apologize for any inconvenience to you and your staff.

Sincerely,

/RA/

Mark A. Ring, Chief
Branch 1
Division of Reactor Projects

Docket Nos. 50-237; 50-249
License Nos. DPR-19; DPR-25

Enclosure: Errata to Inspection Report No. 05000237/2006002;
05000249/2006002

See Attached Distribution

DOCUMENT NAME:E:\Filenet\ML060830065.wpd

☐ Publicly Available

☐ Non-Publicly Available

☐ Sensitive

☐ Non-Sensitive

To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	RIII		RIII				
NAME	ABarker: dtp		MRing				
DATE	03/22/2006		03/22/2006				

OFFICIAL RECORD COPY

cc w/encl: Site Vice President - Dresden Nuclear Power Station
 Dresden Nuclear Power Station Plant Manager
 Regulatory Assurance Manager - Dresden
 Chief Operating Officer
 Senior Vice President - Nuclear Services
 Senior Vice President - Mid-West Regional
 Operating Group
 Vice President - Mid-West Operations Support
 Vice President - Licensing and Regulatory Affairs
 Director Licensing - Mid-West Regional
 Operating Group
 Manager Licensing - Dresden and Quad Cities
 Senior Counsel, Nuclear, Mid-West Regional
 Operating Group
 Document Control Desk - Licensing
 Assistant Attorney General
 Illinois Emergency Management Agency
 State Liaison Officer
 Chairman, Illinois Commerce Commission

ADAMS Distribution:

GYS

MXB

RidsNrrDirslrib

GEG

KGO

DRC1

CAA1

C. Pederson, DRS (hard copy - IR's only)

DRPIII

DRSIII

PLB1

JRK1

ROPreports@nrc.gov (inspection reports, final SDP letters, any letter with an IR number)

ERRATA TO NRC PROBLEM IDENTIFICATION AND RESOLUTION INSPECTION
REPORT 05000237/2006002; 05000249/2006002

1. On Page 1 of the attachment under the heading of “ITEMS OPENED, CLOSED, AND DISCUSSED” insert the following:

ITEMS OPENED, CLOSED, AND DISCUSSED

Items Opened

05000237/2006002-01 05000249/2006002-01	FIN	Failure to enter ERV discrepancies into CAP.
05000237/2006002-02 05000249/2006002-02	NCV	Failure to identify an inadequate surveillance test procedure.
05000237/2006002-03 05000249/2006002-03	URI	Adequacy of licensee’s practice of not performing as-found testing of the ERVs.

Items Closed

05000237/2006002-01 05000249/2006002-01	FIN	Failure to enter ERV discrepancies into CAP.
05000237/2006002-02 05000249/2006002-02	NCV	Failure to identify an inadequate surveillance test procedure.

Items Discussed

None

Enclosure

Enclosure