

Date: April 3, 2006

PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE -- PNO-I-06-005

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region I staff on this date.

Facility

Millstone Unit 2 Power Station
Waterford, CT
Docket: 05000336

Licensee Emergency Classification

☐ Notification of Unusual Event
☐ Alert
☐ Site Area Emergency
☐ General Emergency
☒ Not Applicable

SUBJECT: SHUTDOWN GREATER THAN 72 HOURS - MILLSTONE UNIT 2 TURBINE
DRIVEN AUXILIARY FEEDWATER PUMP ROTATING ASSEMBLY
DEGRADATION

On April 1, 2006, at 7:55 a.m., Millstone Unit 2 removed the turbine generator from operation in conjunction with a shutdown required by Technical Specifications (TS) 3.7.1.2 due to an inoperable turbine-driven auxiliary feedwater pump (TDAFP).

Previously, on March 29, during a planned retest following governor maintenance, the outboard pump bearing of the TDAFP exhibited signs of overheating and high vibrations. An event review team (ERT) was formed to identify root causes and to propose corrective actions while, in parallel, licensee maintenance personnel began to develop a troubleshooting and repair plan. Subsequently, the licensee found the bearing needed replacement. Licensee engineering personnel have evaluated the shaft condition and consider it acceptable for continued use.

During further disassembly activities on March 31, maintenance personnel observed an additional problem with a balancing drum assembly that supports TDAFP operation. This condition, in combination with the degraded bearing, precluded restoring the TDAFP to an operable status prior to the expiration of the TS-allowed outage time at 3:55 a.m., April 1, 2006. Thus, a shutdown to comply with TS was begun at 10:20 p.m., March 31, 2006. As of 11:00 a.m., April 3, 2006, troubleshooting and repair activities are continuing with the plant in Mode 4.

The NRC resident inspector staff have been following TDAFP recovery activities since March 29 and did observe portions of the Unit 2 shutdown and cooldown. The facts of this PN were verified with S. Scace, Nuclear Safety and Licensing Director.

The Region I Public Affairs Office is prepared to respond to media inquiries. The states of Connecticut and New York have been informed.

ADAMS Accession Number: ML060930424

CONTACT: Paul Krohn
(610) 337-5120

DISTRIBUTION: (PN Recipient List)

OWFN

Chairman Diaz

Comm. Lyons

Comm. Jazcko

Comm. McGaffigan Jr.

Comm. Merrifield

OIP

OCA

OGC

OPA

EDO

OE

NRR

SECY

Regional Offices

TWFN

NMSS

ACRS

OIG

RES

NSIR

LST

By Fax:

DOT:Trans

INPO

NSAC

RI Resident Office

Licensee: **Dominion**

ADAMS Accession Number: ML060934424

SISP Review Complete: PGK (Reviewer's Initials)

DOCUMENT NAME: E:\Filenet\ML060930424.wpd

After declaring this document "An Official Agency Record" it **will** be released to the Public.

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RI/DRP		RI/DRP	RI/ORA		RI/DRP		RI/DRP	
NAME	SBarber		RBores	DScrenci		PKrohn		BHolian/GS	
DATE	04/03/06		04/03/06	04/03/06		04/03/06		0403/06	

OFFICIAL RECORD COPY