

July 13, 2006

Mr. T. D. Walt
Vice President
Carolina Power & Light Company
H. B. Robinson Steam Electric Plant Unit 2
3851 West Entrance Road
Hartsville, SC 29550

SUBJECT: H.B. ROBINSON - NRC MATERIAL CONTROL AND ACCOUNTING
PROGRAM INSPECTION - REPORT 05000261/2006201

Dear Mr. Walt:

On April 17-20, 2006, the U.S. Nuclear Regulatory Commission (NRC) conducted a material control and accounting (MC&A) safeguards inspection at your H. B. Robinson Steam Electric Plant (Unit 2) facility. The inspection was conducted under Phase III of Temporary Instruction 2515/154. The enclosed inspection report documents the inspection findings, which were discussed during an exit meeting on April 20, 2006, with you and members of your staff, and in a supplemental exit meeting by telephone on May 22, 2006.

The inspection examined activities conducted under your license as they relate to safety, security and compliance with the Commission's rules and regulations and with the conditions of your license. The inspectors reviewed selected procedures and records, observed storage of special nuclear material in the spent fuel pool, and interviewed personnel. Areas examined during the inspection included physical inventory and accounting records.

This report documents two NRC-identified findings of very low safety significance. These findings were determined to involve violations of NRC requirements. However, because of the very low safety significance and because they are entered into your corrective action program, the NRC is treating these violations as non-cited violations (NCVs), consistent with Section VI.A of the Enforcement Policy. If you contest these non-cited violations, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington DC 20555-0001; with copies to the Regional Administrator, Region II; the Director, Office of Enforcement, United States Nuclear Regulatory Commission, Washington, DC 20555-0001; and the NRC Resident Inspector at the H. B. Robinson Steam Electric Plant.

When separated from the Enclosure, this document is DECONTROLLED.

T. Walt

-2-

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter, will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, this letter's enclosure will not be available for public inspection.

In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response, if any. This practice will ensure that your response will not be made available electronically for public inspection in the NRC Public Document Room or from NRC's document system ADAMS. If Safeguards Information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21. Otherwise, mark your entire response "Security-Related Information - Withhold Under 10 CFR 2.390" and follow the instructions for withholding in 10 CFR 2.390(b)(1).

Should you have any questions concerning this report, please contact Martha Williams at (301) 415-7878 or Dori Votolato (301) 415-7633.

Sincerely,

/RA/

Jeffrey Cruz, Chief
Material Security Oversight Branch
Division of Security Operations
Office of Nuclear Security and Incident Response

Docket No. 50-261
License No. DPR-23

Enclosure: MC&A Inspection Report 05000261/2006201

cc w/enclosure: William G. Noll
C.T. Baucom
Daniel G. Stoddard

cc w/o enclosure: Henry J. Porter, Director

T. Walt

-2-

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter, will be available electronically for public inspection in the NRC Public Document Room or from the Publically Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, this letter's enclosure will not be available for public inspection.

In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response, if any. This practice will ensure that your response will not be made available electronically for public inspection in the NRC Public Document Room or from NRC's document system ADAMS. If Safeguards Information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21. Otherwise, mark your entire response "Security-Related Information - Withhold Under 10 CFR 2.390" and follow the instructions for withholding in 10 CFR 2.390(b)(1).

Should you have any questions concerning this report, please contact Martha Williams at (301) 415-7878 or Dori Votolato (301) 415-7633.

Sincerely,

/RA/

Jeffrey Cruz, Chief
Material Security Oversight Branch
Division of Security Operations
Office of Nuclear Security and Incident Response

Docket No. 50-261
License No. DPR-23

Enclosure: MC&A Inspection Report 05000261/2006201

cc w/enclosure: William G. Noll
C.T. Baucom
Daniel G. Stoddard

cc w/o enclosure: Henry J. Porter, Director

Distribution w/encl:

CAdkison, NSIR
DRiffle, NSIR

CPatel, NRR

DJones, RII

RHagar, RII

Letter and Report:

Document Sensitivity: Sensitive

Availability: Non-Publicly Available

Package: ML061360278, Cover Letter: ML061360294, Report: ML061360301

Log-In #3885

OFFICE	DSO/MSOB	E	DSO/MSOB	E	RII	E	DSO/MSOB	N
NAME	DVotolato		MWilliams		PFredrickson		JCruz	
DATE	06/1/2006		06/1/2006		06/1/2006		06/8/2006	