

July 20, 2006

Mr. H. L. Sumner, Jr.
Vice President - Farley Project
Southern Nuclear Operating
Company, Inc.
Post Office Box 1295
Birmingham, AL 35201-1295

SUBJECT: JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1 AND 2 — CORRECTION OF
RECENTLY ISSUED TECHNICAL SPECIFICATION PAGES

Dear Mr. Summer:

The Nuclear Regulatory Commission (NRC) issued Amendment No. 173 to Renewed Facility Operating License No. NPF-2 and Amendment No. 166 to Renewed Facility Operating License No. NPF-8 (Amendments 173/166) for the Joseph M. Farley Nuclear Plant, Unit 1 and 2 on June 29, 2006. The amendments modified Technical Specification (TS) requirements for inoperable snubbers by modifying Limiting Condition for Operation (LCO) 3.0.1 and adding LCO 3.0.8. Due to the inadvertent use of an outdated version of several TS pages, the issuance of these amendments did not continue to reflect the changes to LCO 3.0.4 and Surveillance Requirement 3.0.4 that was authorized with the issuance of Amendment Nos. 170 and 163 on February 22, 2006. The corrected TS pages 3.0-1, 3.0-2, 3.0-4 and 3.0-5, reflecting both the changes authorized in Amendment Nos. 170/163 and 173/166 are attached.

The NRC also issued Amendment No. 174 to Renewed Facility Operating License No. NPF-2 and Amendment No. 167 to Renewed Facility Operating License No. NPF-8 (Amendments 174/167) for the Joseph M. Farley Nuclear Plant, Unit Nos. 1 and 2 on July 11, 2006. Those amendments revised TS Section 5.6.5, "Core Operating Limits Report (COLR)" to reflect the addition of further methodology for the analysis of loss-of-coolant accidents. Due to the inadvertent use of an outdated version of one TS page, the issuance of these amendments did not continue to reflect the changes to Section 5.6.9 related to containment tendon reporting requirements that had been authorized by Amendments 172/165 on April 14, 2006. The corrected TS page 5.6-6, reflecting both the changes authorized in Amendment Nos. 172/165 and 174/167 is attached.

Sincerely,

/RA/

Robert E. Martin, Senior Project Manager
Plant Licensing Branch II-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket Nos. 50-348 and 50-364

Enclosure: Corrected TS pages 3.0-1, 3.0-2, 3.0-4, 3.0-5 and 5.6-6
cc w/encl: See next page

Mr. H. L. Sumner, Jr.
Vice President - Farley Project
Southern Nuclear Operating
Company, Inc.
Post Office Box 1295
Birmingham, AL 35201-1295

SUBJECT: JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1 AND 2 — CORRECTION OF
RECENTLY ISSUED TECHNICAL SPECIFICATION PAGES

Dear Mr. Summer:

The Nuclear Regulatory Commission (NRC) issued Amendment No. 173 to Renewed Facility Operating License No. NPF-2 and Amendment No. 166 to Renewed Facility Operating License No. NPF-8 (Amendments 173/166) for the Joseph M. Farley Nuclear Plant, Unit 1 and 2 on June 29, 2006. The amendments modified Technical Specification (TS) requirements for inoperable snubbers by modifying Limiting Condition for Operation (LCO) 3.0.1 and adding LCO 3.0.8. Due to the inadvertent use of an outdated version of several TS pages, the issuance of these amendments did not continue to reflect the changes to LCO 3.0.4 and Surveillance Requirement 3.0.4 that was authorized with the issuance of Amendment Nos. 170 and 163 on February 22, 2006. The corrected TS pages 3.0-1, 3.0-2, 3.0-4 and 3.0-5, reflecting both the changes authorized in Amendment Nos. 170/163 and 173/166 are attached.

The NRC also issued Amendment No. 174 to Renewed Facility Operating License No. NPF-2 and Amendment No. 167 to Renewed Facility Operating License No. NPF-8 (Amendments 174/167) for the Joseph M. Farley Nuclear Plant, Unit Nos. 1 and 2 on July 11, 2006. Those amendments revised TS Section 5.6.5, "Core Operating Limits Report (COLR)" to reflect the addition of further methodology for the analysis of loss-of-coolant accidents. Due to the inadvertent use of an outdated version of one TS page, the issuance of these amendments did not continue to reflect the changes to Section 5.6.9 related to containment tendon reporting requirements that had been authorized by Amendments 172/165 on April 14, 2006. The corrected TS page 5.6-6, reflecting both the changes authorized in Amendment Nos. 172/165 and 174/167 is attached.

Sincerely,

/RA/

Robert E. Martin, Senior Project Manager
Plant Licensing Branch II-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket Nos. 50-348 and 50-364

Enclosure: Corrected TS pages 3.0-1, 3.0-2, 3.0-4, 3.0-5 and 5.6-6

cc w/encl: See next page

DISTRIBUTION:

Public
LPL2-1 R/F
RidsNrrDorlPl2-1 (EMarinos)
RidsNrrPMRMartin(hard copy)
RidsNrrLARSola(hard copy)
Accession No.: ML062060257 Tech Spec No. ML062020715 Package No. 062050512

RidsAcrsAcnwMailCenter RidsNrrPMSLingam
G. Hill, OIS (4 hard copies) RidsNrrDorlDpr (BSingal)
RidsNrrDirsltsb (TKobetz) RidsOgcRp
T. Tjader, NRR
S. Samaddar, NRR F. Orr, NRR
RidsRgn2MailCenter(SShaeffer)

OFFICE	NRR/LPL2-1/PM	NRR/LPL2-1/LA	NRR/LPL2-1/BC
NAME	RMartin	RSola	EMarinos
DATE	7/20/06	7/19/06	7/20/06

OFFICIAL RECORD COPY

CORRECTED TECHNICAL SPECIFICATION PAGES
FOR RENEWED FACILITY OPERATING LICENSE NO. NPF-2
DOCKET NO. 50-348
AND RENEWED FACILITY OPERATING LICENSE NO. NPF-8
DOCKET NO. 50-364

Replace the following pages of the Appendix A Technical Specifications (TSs) with the attached corrected pages.

Remove
TSs Pages

3.0-1
3.0-2
3.0-4
3.0-5
5.6-6

Insert
TSs Pages

3.0-1
3.0-2
3.0-4
3.0-5
5.6-6

Joseph M. Farley Nuclear Plant, Units 1 & 2

cc:

Mr. J. R. Johnson
General Manager
Southern Nuclear Operating Company, Inc.
P.O. Box 470
Ashford, AL 36312

Mr. B. D. McKinney, Licensing Manager
Southern Nuclear Operating Company, Inc.
P.O. Box 1295
Birmingham, AL 35201-1295

Mr. M. Stanford Blanton
Balch and Bingham Law Firm
P.O. Box 306
1710 Sixth Avenue North
Birmingham, AL 35201

Mr. J. Gasser
Executive Vice President
Southern Nuclear Operating Company, Inc.
P.O. Box 1295
Birmingham, AL 35201

State Health Officer
Alabama Department of Public Health
434 Monroe St.
Montgomery, AL 36130-1701

Chairman
Houston County Commission
P.O. Box 6406
Dothan, AL 36302

Resident Inspector
U.S. Nuclear Regulatory Commission
7388 N. State Highway 95
Columbia, AL 36319