



3377 Hollenberg Drive
Bridgeton, Missouri 63044
www.mwtesting.com

314 739-2727 Office
314 739-5429 Fax
314 739-8589 Accounting Fax

GEOTECHNICAL
ENVIRONMENTAL
MATERIALS

July 24, 2006

Bureau of Radiological Health
Iowa Department of Public Health
321 East 12th Street
Lucas State Office Building
Des Moines, IA 50319

Attn; Mr. Randal S. Dahlin
Mr. Donald A Flater

Re: Reciprocity—Iowa #9112-1-00-PG
Material License #24-24619-02 NRC
Midwest Testing, Inc.
3377 Hollenberg Drive
Bridgeton, Missouri 63044

Dear Sirs,

Enclosed please note the following information regarding our response to the field-inspection conducted by Randal S. Dahlin on 7-11-06.

Violation # 1;

Additional securing of the portable gauge was added the same day of the referenced inspection. A second locked chain now secures the locked storage container in the bed of the company work truck, during working hours. Overnight storage involves the locked container, cable locked into the locked truck bed work box. Technician user was reminded to always secure the gauge by the above means while not under constant surveillance.

Violation # 2;

The manufacturers 800 Emergency Number was added to the current Iowa users Shipping Paper the same day of inspection. We do supply the number in each of the transport cases. In conjunction we contract with Chem-Tel for our Emergency Response

RECEIVED AUG 01 2006

support. Unfortunately the Shipping Paper supplied to the current Iowa user did not include this Emergency Number. Please see attached, OLD and NEW Shipping Paper support documents.

Violation # 3;

The incorrect UN number was added to the current Iowa user the same day of inspection. Unfortunately this was an oversight on my part with the continuing changes in DOT numbers, placarding, etc. Please see attached, old and NEW Shipping Paper support documents. All of our Shipping Papers, company wide, have been updated to reflect current UN number.

As of this written response, our Iowa user has informed me that a re-inspection has been conducted to your satisfaction.

Please address any other issues to me, for my prompt attention.



David L. Weber
RSO, Soils Supervisor

Cc:

James I. Lynch
Regional Sate Agreements Officer
Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532

Enclosures:

1. Response Letter of Violations
2. Shipping Paper Documents

OR TRANSPORTATION EMERGENCY
CONTACT:
HEM•TEL INC. 1-800-255-3924



3377 Hollenberg Drive • Bridgeton, Missouri 63044 • 314-739-2727 • Fax 314-739-5429

Geotechnical • Environmental • Materials

SHIPPING PAPER

Case, RADIOACTIVE MATERIAL, R.Q.
SPECIAL FORM. N.O.S., UN2974, CLASS 7

Cs-137 100mCi

Am-241 700, 50 mCi

RADIOACTIVE YELLOW-H Label

Transport Index 0.4

USA DOT 7 A TYPE A Package

RSO: David L. Weber (314)-739-2727 Ext. 29

AFTER HOURS CONTACTS:

David L. Weber

Home: (636) 928-8139

Mobile: (314) 574-0437

Richard D. Laughlin, P.E.

Home: (314) 532-7967

Mobile: (314) 220-5819

The above contacts should be attempted first in any case. If that is not possible then additional direct NRC emergency response numbers are enclosed in each gauge container, listed in the "Standard Operating and Emergency Procedures." These numbers should be used if the gauge structure is crushed, severely damaged, and the integrity of the source is in doubt.

USERS: Authorized employees of Midwest Testing, Inc. in route to or on various construction sites in the United States.

Midwest Testing, Inc.

OLD

3377 Hollenberg Drive
Bridgeton, Missouri 63044
www.mwtesting.com

314 739-2727 Office
314 739-5429 Fax
314 739-8589 Accounting Fax



GEOTECHNICAL
ENVIRONMENTAL
MATERIALS

SHIPPING PAPER

Case, RADIOACTIVE MATERIAL, R.Q.
SPECIAL FORM, N.O.S., UN3332, CLASS 7
Cs-137, 10 mCi
Am-241/Be, 40 or 50 mCi
RADIOACTIVE YELLOW-II Label
Transport Index 0.2 or 0.4
USA DOT 7 A TYPE A Package

RSO: David L. Weber (314)-739-2727

AFTER HOURS CONTACTS:


David L. Weber	Home: (636) 978-1567
	Mobile: (314) 574-0437

Richard D. Laughlin, P.E.	Home: (314) 532-7967
	Mobile: (314) 220-5819

The above contacts should be attempted first in any case. If that is not possible then additional direct NRC emergency response numbers are enclosed in each gauge container, listed in the "Standard Operating and Emergency Procedures." These numbers should be used if the gauge structure is crushed, severely damaged, and the integrity of the source is in doubt.

Transportation Emergency 24 Hrs; CHEM TEL INC 1-800-255-3924

USERS: Authorized employees of Midwest Testing, Inc. in route to or on various construction sites in the United States.



neopost 045J83053256
\$0.630
07/26/2006
Mailed From 63044
US POSTAGE

3377 Hollenberg Drive
Bridgeton, Missouri 63044



Midwest
Testing

GEOTECHNICAL
ENVIRONMENTAL
MATERIALS

James Lynch
Nuclear Regulatory Commission
2443 Warrenville Road
Suite 210
Lisle, IL 60532