

SAFEGUARDS INFORMATION

August 10, 2006

Mr. Terry Jones
Site Vice President
Turkey Point Nuclear Generating Station
Florida Power & Light Company
9760 SW 344th Street
Florida City, FL 33035

SUBJECT: TURKEY POINT NUCLEAR GENERATING STATION - SECURITY
INSPECTION 05000250/2006201 AND 05000251/2006201

Dear Mr. Jones:

On June 23, 2006, the U.S. Nuclear Regulatory Commission (NRC) completed a security baseline inspection at the Turkey Point Nuclear Generating Station. The inspection covered one or more of the key attributes of the security cornerstone of the NRC's Reactor Oversight Process. The enclosed inspection report documents the inspection results, which were discussed on June 23, 2006, with you and other members of your staff.

The inspection examined activities conducted under your license as they relate to security and compliance with the Commission's rules and regulations and with the conditions of your license. The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel. No findings of significance were identified.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system, ADAMS. ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosure will not be available for public inspection.

Enclosure contains <u>Safeguards Information</u> . Upon removal, this letter is decontrolled.
--

SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

T. Jones

-2-

Should you have any questions concerning this letter, please contact us. Your cooperation is appreciated.

Sincerely,

/RA/

Ronald J. Albert, Chief
Security Performance Evaluation Branch
Security Oversight
Division of Security Operations
Office of Nuclear Security and Incident Response

Docket Nos.: 50-250 and 50-251
License Nos.: DPR-31 and DPR-41

Enclosure: NRC Inspection Report No. 05000250/2006201 and 05000251/2006201

cc w/encl: Guy M. Tunnell
William A. Passetti
Nick Eggemeyer, Security Manager

cc w/o encl: Walter Parker, Site Licensing Manager
Don Mothena, Corporate Emergency Planning Coordinator
Milt Murray, Emergency Planning Coordinator

SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

T. Jones

-2-

Should you have any questions concerning this letter, please contact us. Your cooperation is appreciated.

Sincerely,

/RA/

Ronald J. Albert, Chief
Security Performance Evaluation Branch
Security Oversight
Division of Security Operations
Office of Nuclear Security and Incident Response

Docket Nos.: 50-250 and 50-251
License Nos.: DPR-31 and DPR-41

Enclosure: NRC Inspection Report No. 05000250/2006201 and 05000251/2006201

cc w/encl: Guy M. Tunnell
William A. Passetti
Nick Eggemeyer, Security Manager

cc w/o encl: Walter Parker, Site Licensing Manager
Don Mothena, Corporate Emergency Planning Coordinator
Milt Murray, Emergency Planning Coordinator

Distribution w/encl:

SPEB R/F - C. Grigsby, SPEB
K. Grimes, RSS
B. Bonser, R-II

B. Westrich, SOS
S. Stewart, SRI Turkey Point

Distribution w/o encl:

B. Moroney, PM - NRR
C. Adkison - PMDA

Accession No.: ML062260018

OFC:	DSO/SPEB		SRI Turkey Point		Region II		DSO/SPEB	
NAME:	A. Rayland		S. Stewart		B. Bonser		R. Albert	
DATE:	7/25/06		8/10/06		8/10/06		8/10/06	

OFFICIAL RECORD COPY

SAFEGUARDS INFORMATION