

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Advanced GeoServices Corporation
West Chester, Pennsylvania 19380

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region I, 475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

REPORT Nos 2006-001

3. DOCKET NUMBER(S)

030-32977

4. LICENSE NUMBER(S)

37-28800-01

5. DATE(S) OF INSPECTION

06- 22, & 07-20- 2006

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.
- ☐ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☒ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

License Condition No. 20 requires that licensed material be transported in accordance with the provisions of 10CFR Part 71

Contrary to the above, on 07-20-06 a Troxler gauge was transported to a temporary field site in West Bradford Township, Pa. with out the necessary transportation papers to include a bill of lading.

- CONDITION WAS CORRECTED THE SAME DAY - TRANSPORT PAPERS WERE PROVIDED.
- ADDITIONAL STAFF TRAINING WILL ALSO BE CONDUCTED TO ADDRESS THIS PROBLEM.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	PAUL F. MARANO	<i>Paul F. Marano</i>	7-25-06
NRC INSPECTOR	Richard H. Ladun	<i>Richard H. Ladun</i>	07-25-06