

Dave Everhart - Corrective Action regarding Troxler Gauge

From: "Beatty, Chuck" <CBeatty@PIRNIE.COM>
To: <dbe@nrc.gov>
Date: 08/15/2006 9:17 AM
Subject: Corrective Action regarding Troxler Gauge
CC: "Shuckrow, Alan" <AShuckrow@PIRNIE.COM>, "Golden, Joseph" <JGolden@PIRNIE.COM>

Mr. Everhart:

Based on our August 10, 2006 telephone conversation regarding security of Malcolm Pirnie's Troxler Gauge at the MolyCorp site, it is our understanding that the restricted access gate and full time security guard are not deemed acceptable as an independent physical control pursuant to Appendix H (in addition to the locked room in the trailer). Therefore, at your suggestion, we have installed the following additional physical control:

the Troxler Case is secured to the floor of the locked room via a ¼" chain attached to a ¼" O-ring attached to a floor joist. The chain is strung through all three handles of the case, tightened, and locked. I've attached photographs for your review.

Please let me know if you need anything further.

Sincerely

Chuck Beatty
Senior Construction Manager
Malcolm Pirnie, Inc.
412-716-3701