



**UNITED STATES  
NUCLEAR REGULATORY COMMISSION**

REGION III  
2443 WARRENVILLE ROAD, SUITE 210  
LISLE, ILLINOIS 60532-4352

September 6, 2007

Ms. Deb Noblett, BSN, MBA  
Practice Administrator  
Michigan Heart & Vascular Specialists, P.C.  
A.K.A. Petoskey Cardiology, P.C.  
560 West Mitchell Street, Suite 400  
Petoskey, MI 49770

SUBJECT: NRC INSPECTION REPORT 030-35824/07-01 (FORM 591M Part 1)  
MICHIGAN HEART & VASCULAR SPECIALISTS, P.C.; A.K.A. PETOSKEY  
CARDIOLOGY, P.C.

Dear Ms. Noblett:

This letter refers to the routine inspection conducted on August 7, 2007, at your Petoskey, Michigan facility. The inspection also included a review of the circumstances surrounding the reported loss of a 15 millicurie dose of Technetium-99m in October 2006. Based on your written report to the incident, dated November 7, 2006, you believed that the dose was never received by the facility. However, in order to identify any discrepancies between the packing slip and the actual doses received, you revised the radioactive material receipt procedure to include verifying that the number of doses received agrees with the packing slip, documenting the agreement and initialing the notation. The preliminary inspection results were discussed with you at the conclusion of the inspection on August 7, 2007. A final telephonic exit meeting was held with you on September 5, 2007.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, independent measurements, and observation of activities in progress. Within the scope of this inspection no violations of NRC requirements were identified; therefore, no response to this letter or the enclosed NRC Form 591M Part 1 is required.


In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

D. Noblett

-2-

Should you have any questions concerning this inspection or the enclosed report, please contact Ken Lambert of my staff at (630) 829-9633.

Sincerely,

A handwritten signature in black ink, appearing to read "John R. Madera". The signature is fluid and cursive, with a large loop at the beginning and a long horizontal stroke at the end.

John R. Madera, Chief  
Materials Inspection Branch

Docket No.: 030-35824  
License No.: 21-32345-01

Enclosure:  
Inspection Report 030-35824/07-01 (Form 591M Part 1)

cc w/encl: State of Michigan

(10-2003)  
10 CFR 2.201

## SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

8/5/07

## 1. LICENSEE/LOCATION INSPECTED:

**Michigan Heart & Vascular Specialists, P.C.  
AKA Petoskey Cardiology, P.C.  
560 West Mitchell  
Petoskey, MI**

## 2. NRC/REGIONAL OFFICE

**U.S. Nuclear Regulatory Commission  
Region III  
2443 Warrenville Road  
Suite 210  
Lisle, Illinois 60532-4351**

REPORT 07-01

## 3. DOCKET NUMBER(S)

030-35824

## 4. LICENSEE NUMBER(S)

21-32345-01

## 5. DATE(S) OF INSPECTION

08/07/2007

## LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- X 1. Based on the inspection findings, no violations were identified.
2. Previous violation(s) closed.
3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

## Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title

Printed Name

Signature

Date

LICENSEE'S  
REPRESENTATIVE

NRC INSPECTOR

Ken Lambert

Ken Lambert

9/5/07