

September 28, 2007

Mr. James A. Spina, Vice President
Calvert Cliffs Nuclear Power Plant, Inc.
Calvert Cliffs Nuclear Power Plant
1650 Calvert Cliffs Parkway
Lusby, MD 20657-4702

SUBJECT: CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT NOS. 1 AND 2 -
CORRECTION TO AMENDMENT NOS. 278 AND 255 RE: STEAM
GENERATOR TUBE INTEGRITY (TAC NOS. MC8067 AND MC8068)

Dear Mr. Spina:

On March 9, 2006, the Commission issued Amendment No. 278 to Renewed Facility Operating License No. DPR-53 and Amendment No. 255 to Renewed Facility Operating License No. DPR-69 for the Calvert Cliffs Nuclear Power Plant, Unit Nos. 1 and 2. These amendments were in response to your application dated July 13, 2005, as supplemented on November 29, 2005, and January 20 and February 13, 2006. These amendments revised Technical Specification (TS) 1.1, "Definitions," TS 3.4.13, "RCS [reactor coolant system] Operational Leakage," TS 5.5.9, "Steam Generator Tube Surveillance Program," TS 5.6.9, "Steam Generator Tube Inspection Report," and added new TS 3.4.18, "Steam Generator (SG) Tube Integrity."

The list of affected TS pages attached to the amendment only addressed those pages which were revised as a result of the amendments and inadvertently failed to identify those pages which should have been deleted. Subsequently, you informed us that certain pages in TS 5.5.9 are no longer applicable. Therefore, we have enclosed the list of TS pages to be deleted.

We apologize for any inconvenience this may have caused. If there are any questions regarding this matter, please contact me at (301) 415-1364.

Sincerely,

/RA/

Douglas V. Pickett, Senior Project Manager
Plant Licensing Branch I-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket Nos. 50-317 and 50-318

Enclosure:
As stated

cc w/encl: See next page

Calvert Cliffs Nuclear Power Plant, Unit Nos. 1 and 2

cc:

Mr. Michael J. Wallace, President
Constellation Generation Group
750 East Pratt Street
Baltimore, MD 21202

Mr. John M. Heffley
Senior Vice President and
Chief Nuclear Officer
Constellation Generation Group
1997 Annapolis Exchange Parkway
Suite 310
Annapolis, MD 21401

President
Calvert County Board of
Commissioners
175 Main Street
Prince Frederick, MD 20678

Mr. Carey Fleming, Esquire
Sr. Counsel - Nuclear Generation
Constellation Generation Group, LLC
750 East Pratt Street, 17th floor
Baltimore, MD 21202

Mr. Jay S. Gaines
Director, Licensing
Calvert Cliffs Nuclear Power Plant
1650 Calvert Cliffs Parkway
Lusby, MD 20657-4702

Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 287
St. Leonard, MD 20685

Mr. R. I. McLean, Manager
Nuclear Programs
Power Plant Research Program
Maryland Department of Natural Resources
580 Taylor Avenue (B wing, 3rd floor)
Tawes State Office Building
Annapolis, MD 21401

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road

King of Prussia, PA 19406

Ms. Kristen A. Burger, Esquire
Maryland People's Counsel
6 St. Paul Centre
Suite 2102
Baltimore, MD 21202-1631

Ms. Patricia T. Birnie, Esquire
Co-Director
Maryland Safe Energy Coalition
P.O. Box 33111
Baltimore, MD 21218

Mr. Roy Hickok
NRC Technical Training Center
5700 Brainerd Road
Chattanooga, TN 37411-4017

September 28, 2007

Mr. James A. Spina, Vice President
Calvert Cliffs Nuclear Power Plant, Inc.
Calvert Cliffs Nuclear Power Plant
1650 Calvert Cliffs Parkway
Lusby, MD 20657-4702

SUBJECT: CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT NOS. 1 AND 2 -
CORRECTION TO AMENDMENT NOS. 278 AND 255 RE: STEAM
GENERATOR TUBE INTEGRITY (TAC NOS. MC8067 AND MC8068)

Dear Mr. Spina:

On March 9, 2006, the Commission issued Amendment No. 278 to Renewed Facility Operating License No. DPR-53 and Amendment No. 255 to Renewed Facility Operating License No. DPR-69 for the Calvert Cliffs Nuclear Power Plant, Unit Nos. 1 and 2. These amendments were in response to your application dated July 13, 2005, as supplemented on November 29, 2005, and January 20 and February 13, 2006. These amendments revised Technical Specification (TS) 1.1, "Definitions," TS 3.4.13, "RCS [reactor coolant system] Operational Leakage," TS 5.5.9, "Steam Generator Tube Surveillance Program," TS 5.6.9, "Steam Generator Tube Inspection Report," and added new TS 3.4.18, "Steam Generator (SG) Tube Integrity."

The list of affected TS pages attached to the amendment only addressed those pages which were revised as a result of the amendments and inadvertently failed to identify those pages which should have been deleted. Subsequently, you informed us that certain pages in TS 5.5.9 are no longer applicable. Therefore, we have enclosed the list of TS pages to be deleted.

We apologize for any inconvenience this may have caused. If there are any questions regarding this matter, please contact me at (301) 415-1364.

Sincerely,
/RA/

Douglas V. Pickett, Senior Project Manager
Plant Licensing Branch I-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket Nos. 50-317 and 50-318

Enclosure:
As stated

cc w/encl: See next page

DISTRIBUTION:

PUBLIC	RidsNrrDorLpl1-1	RidsNrrLASLittle
LPL1-1 R/F	RidsNrrPMDPickett	GHill (2)
OGC	ACRS	GDentel, R1

Accession Number: ML072620215

OFFICE	LPL1-1	LPL1-1/PM	LPL1-1/LA	LPL1-1/BC
NAME	DWoodyatt	DPickett	SLittle	MKowal
DATE	09/26 /07	09/ 26 /07	09/ 26 /07	09/ 28 /07

Official Record Copy

ATTACHMENT TO LICENSE AMENDMENTS

AMENDMENT NO. 278 TO RENEWED FACILITY OPERATING LICENSE NO. DPR-53

AMENDMENT NO. 255 TO RENEWED FACILITY OPERATING LICENSE NO. DPR-69

DOCKET NOS. 50-317 AND 50-318

Remove the following pages from the Appendix A Technical Specifications.

<u>Remove</u>	<u>Insert</u>
5.5-19	—
5.5-20	—
5.5-21	—
5.5-22	—
5.5-23	—
5.5-24	—

Enclosure