



September 23, 2009

Docket No. 50-443

Docket No. 72-63

SBK-L-09210

United States Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, D.C. 20555-0001

Seabrook Station
Procedure OS1290.03 and OS1290.04


In accordance with the requirements of 10 CFR 50, Appendix E, 10 CFR 50.4 and 10 CFR 72.44(f), enclosed is procedure OS1290.03, Response to a Security Event, Revisions 6 and 7 and procedure OS1290.04, Response to an Airborne Security Event, Revisions 2 and 3. The procedure is used in the implementation of the Seabrook Station Radiological Emergency Plan (SSREP). The procedure, as changed, does not decrease the effectiveness of the SSREP and the SSREP continues to meet the standards of 10 CFR 50.47(b) and 10 CFR 50, Appendix E. The Resident Inspector copy is provided directly through the NextEra Energy Seabrook, LLC (NextEra) records management system.

Enclosure 1 provides a summary of changes to procedures OS1290.03 and OS1290.04. Enclosure 2 is a copy of the revised procedure. Because the enclosed procedure contains security-related information, NextEra requests that this submittal be withheld from public disclosure in accordance with 10 CFR 2.390(d)(1).

Should you have any questions regarding the enclosed revisions, please contact me at (603) 773-7745.


Very truly yours,

NextEra Energy Seabrook, LLC



Michael O'Keefe
Licensing Manager

8001
NMSS01
AX45
NMSS



United States Nuclear Regulatory Commission
SBK-L-09210 / Page 2

cc (with enclosures):

S. T. Barr, Region I, Division of Reactor Safety (two copies)

D. Egan, NRC Project Manager, Project Directorate I-2

cc (without Enclosure 2):

ATTN: Document Control Desk

Director, Spent Fuel Storage and Transportation,

Office of Nuclear Material Safety and Safeguards

Nuclear Regulatory Commission

Washington, DC 20555-0001

cc (without enclosures):

S. J. Collins, NRC Region I Administrator

W. J. Raymond, NRC Senior Resident Inspector



Enclosure 1 to SBK-L-09210

Procedure OS1290.03 Summary of Changes

Rev. 7

- Reinstated information in Rev. 6. Pager system described in Rev. 30 is not ready for implementation

Rev. 6

- Changed the pager activation process to recognize use of the American Messaging paging service. This affected Form C notification processes by changing the pager group call numbers, eliminating the alternate group call number, and replacing the alternate call method for an initial failure with a website activation process before using the manual method.

Procedure OS1290.04 Summary of Changes

Rev. 3

- Reinstated information in Rev. 1. Pager system described in Rev. 30 is not ready for implementation

Rev. 2

- Changed the pager activation process to recognize use of the American Messaging paging service. This affected Form C notification processes by changing the pager group call numbers, eliminating the alternate group call number, and replacing the alternate call method for an initial failure with a website activation process before using the manual method.