

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8102030581 DOC.DATE: 81/01/28 NOTARIZED: NO DOCKET #
 FACIL:50-305 Kewaunee Nuclear Power Plant, Wisconsin Public Service 05000305
 AUTH.NAME AUTHOR AFFILIATION
 SMOKER,C.S. Wisconsin Public Service Corp.
 RECIP.NAME RECIPIENT AFFILIATION
 Region 3, Chicago, Office of the Director

SUBJECT: LER 80-044/03L-0: on 801229, noted that RCS oxygen sample test not performed w/frequency required by Tech Specs. Caused by personnel error. Personnel will be instructed in implementation of procedure.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 141
 TITLE: Incident Reports

NOTES: I&E: 3 copies all material.

05000305

ACTION:	RECIPIENT ID CODE/NAME		COPIES		RECIPIENT ID CODE/NAME	COPIES	
			LTTR	ENCL		LTTR	ENCL
	VARGA, S.	04	3	3			
INTERNAL:	A/D COMP&STRU06		1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08		1	1	A/D OP REACT009	1	1
	A/D PLANT SYS10		1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12		1	1	A/D TECHNOLOG13	1	1
	ACC EVAL BR 14		1	1	AEOD	3	3
	ASLBP/J.HARD		1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16		1	1	CONT SYS BR 17	1	1
	CORE PERF BR 18		1	1	DIR, DIV OF LIC	1	1
	DIR, ENGINEER120		1	1	DIR, HUM FAC S21	1	1
	DIR, SYS INTEG22		1	1	EFF TR SYS BR23	1	1
	EQUIP QUAL BR25		1	1	GEOSCIENCES 26	1	1
	I&C SYS BR 29		1	1	I&E 05	3	3
	JORDAN, E./IE		1	1	LIC GUID BR 30	1	1
	MATL ENG BR 32		1	1	MECH ENG BR 33	1	1
	MPA		3	3	NRC PDR 02	1	1
	OP EX EVAL BR34		3	3	OR ASSESS BR 35	1	1
	POWER SYS BR 36		1	1	RAD ASSESS BR39	1	1
	REACT SYS BR 40		1	1	REG FILE 01	1	1
	REL & RISK A 41		1	1	SFTY PROG EVA42	1	1
	STRUCT ENG BR44		1	1	SYS INTERAC B45	1	1
EXTERNAL:	ACRS	46	16	16	LPDR 03	1	1
	NSIC	05	1	1	TERA:DOUG MAY	1	1

FEB 04 1981

TOTAL NUMBER OF COPIES REQUIRED: LTTR

70 ENCL 70

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

January 28, 1981

Mr. J. G. Keppler, Regional Director
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305
Operating License DPR-43
Reportable Occurrence LER 80-044

In accordance with the requirements of Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence LER 80-044/03L-0 is being submitted.

Very truly yours,

E. R. Mathews

E. R. Mathews, Vice President
Power Supply & Engineering

snf

Attach.

cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, DC 20555
Dir, Office of Mgt Info & Program Control
US NRC, Washington, DC 20555
Mr. W. Lavalley, NSAC
PO Box 10412, Palo Alto, CA 94303
Mr. Robert Nelson, NRC Resident Inspector
RR #1, Box 999, Kewaunee, WI 54216

A002
5
1/1

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	W	I	K	N	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	9					14	15											25	26					30		57	CAT	58
LICENSE CODE		LICENSE NUMBER														LICENSE TYPE													

CON'T

REPORT SOURCE L 6 0 5 0 0 0 3 0 5 7 1 2 2 9 8 0 8 0 1 2 8 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 The RCS O₂ sample test was performed only twice during the week ending 12-26-80.

0 3 This is not in accordance with the Surveillance requirements of T.S. 4.1.b and

0 4 Table T.S. 4.1-2 which requires the sample test to be performed three times per

0 5 week, minimum, with a maximum of four days between sample tests. The maximum of

0 6 four days between sample tests was not exceeded. Subsequent sample tests showed O₂

0 7 concentrations within T.S. limits. There was no effect on public safety or plant

0 8 operation.

SYSTEM CODE C G (11)		CAUSE CODE A (12)		CAUSE SUBCODE X (13)		COMPONENT CODE Z Z Z Z Z Z (14)						COMP. SUBCODE Z (15)		VALVE SUBCODE Z (16)			
EVENT YEAR 8 0 (21)		SEQUENTIAL REPORT NO. 0 4 4 (24)		OCCURRENCE CODE 0 3 (28)		REPORT TYPE L (30)		REVISION NO. 0 (32)									
ACTION TAKEN H (18)		FUTURE ACTION Z (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22)		ATTACHMENT SUBMITTED N (23)		NPRD-4 FORM SUB. N (24)		PRIME COMP. SUPPLIER Z (25)		COMPONENT MANUFACTURER Z 9 9 9 (26)	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
1	5	G	28	0	0	0	29	NA	B	31	Administrative review	32
7	8	9	10	11	12	13	14	15	16	17	18	19
ACTIVITY CONTENT		RELEASED OF RELEASE			AMOUNT OF ACTIVITY		LOCATION OF RELEASE					
1	6	Z	33	Z	34	NA	NA					
7	8	9	10	11	12	13	14	15	16	17	18	19
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION						
1	7	0	0	0	37	Z	38	NA				
7	8	9	10	11	12	13	14	15	16	17	18	19
PERSONNEL INJURIES		NUMBER		DESCRIPTION								
1	8	0	0	0	40	NA						
7	8	9	10	11	12	13	14	15	16	17	18	19
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION								
1	9	Z	42	NA								
7	8	9	10	11	12	13	14	15	16	17	18	19
PUBLICITY		ISSUED		DESCRIPTION								
2	0	W	44	NA								
7	8	9	10	11	12	13	14	15	16	17	18	19
NRC USE ONLY												

NAME OF PREPARER C. S. Smoker

PHONE: (414) 388-2560

917-928