

Comanche Peak Nuclear Power Plant, Units 3 & 4
COL Application
Part 2, FSAR

1Hz+2.5Hz, 10^{-5}




Figure 2.5.2-226 Deaggregation of 10^{-5} Rock Hazard for 1 and 2.5 Hz