

Comanche Peak Nuclear Power Plant, Units 3 & 4  
COL Application  
Part 2, FSAR




Figure 2.5.2-227 Deaggregation of  $10^{-6}$  Rock Hazard for 5 and 10 Hz