

FILE:

FROM: Iowa Electric Light & Power Co. Cedar Rapids, IO G. G. Hunt		DATE OF DOC 7-16-74	DATE REC'D 7-22-74	LTR X	TWX	RPT	OTHER
TO: James Keppler		ORIG 1	CC	OTHER	SENT AEC PDR XXX SENT LOCAL PDR XXX		
CLASS	UNCLASS	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-331		
DESCRIPTION: Ltr furn info re abnormal occurrence rpt #A050-331/74-19 re inoperable scram switch....				ENCLOSURES:			
PLANT NAME: DUANE ARNOLD				ACKNOWLEDGED DO NOT REMOVE			

FOR ACTION/INFORMATION 7-22-74 GMC

BUTLER (L)	SCHWENCER (L)	ZIEMANN (L)	REGAN (E)
W/ CYS	W/ CYS	W/ CYS	W/ CYS
CLARK (L)	STOLZ (L)	DICKER (E)	✓LEAR
W/ CYS	W/ CYS	W/ CYS	W/ 7 CYS
W/ CYS	VASSALLO (L)	KNIGHTON (E)	
W/ CYS	W/ CYS	W/ CYS	W/ CYS
KNIEL (L)	PURPLE (L)	YOUNGBLOOD (E)	
W/ CYS	W/ CYS	W/ CYS	W/ CYS

INTERNAL DISTRIBUTION

✓REG FILE	✓TECH REVIEW	DENTON	LIC ASST	A/T IND
✓AEC PDR	✓HENDRIE	GRIMES	DIGGS (L)	BRAITMAN
✓CGC	✓SCHROEDER	GAMMILL	GEARIN (L)	SALTZMAN
✓MUNTZING/STAFF	✓MACCARY	KASTNER	GOULBOURNE (L)	B. HURT
✓CASE	✓KNIGHT	BALLARD	KREUTZER (E)	
GIAMBUSSO	✓PAWLICKI	SPANGLER	LEE (L)	PLANS
BOYD	✓SHAO		MAIGRET (L)	MCDONALD
MOORE (L)(LWR-2)	✓STELLO	ENVIRO	REED (E)	CHAPMAN
DEYOUNG (L)(LWR-1)	✓HOUSTON	MULLER	SERVICE (L)	DUBE w/input
✓SKOVHOLT (L)	✓NOVAK	DICKER	SHEPPARD (L)	E. COUPE
✓COLLER (L)	✓ROSS	KNIGHTON	SLATER (E)	
P. COLLINS	✓IPPOLITO	YOUNGBLOOD	SMITH (L)	✓D. THOMPSON (2)
DENISE	✓TEDESCO	REGAN	✓TEETS (L)	✓KLECKER
✓REG OPR	✓LONG	PROJECT MGR	WILLIAMS (E)	✓EISENHUT
✓FILE & REGION (3)	✓LAINAS		WILSON (L)	
✓MORRIS	✓BENAROYA	HARLESS		
✓STEELE	✓VOLLMER			


EXTERNAL DISTRIBUTION

✓1 - LOCAL PDR CEDAR RAPIDS, IO	(1)(2)(10)-NATIONAL LABS	1-PDR-SAN/LA/NY
✓1 - TIC (ABERNATHY)	1-ASLBP(E/W Bldg, Rm 529)	1-BROOKHAVEN NAT LAB
✓1 - NSIC (BUCHANAN)	1-W. PENNINGTON, Rm E-201 GT	1-G. ULRIKSON, ORNL
1 - ASLB	1-B&M SWINEBROAD, Rm E-201 GT	1-AGMED (RUTH GUSMAN)
✓1 - P. R. DAVIS	1-CONSULTANTS	Rm B-127 GT
✓16 - ACRS SENT TO LIC ASST TEETS 7-23-74	NEWARK/BLUNE/AGBAELAN	1-RD..MUELLER, Rm F-300
		GT

REGULATORY DOCKET FILE COPY
IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office
CEDAR RAPIDS, IOWA
DUANE ARNOLD ENERGY CENTER
PALO, IOWA
July 16, 1974
DAEC - 74 - 253

Mr. James Keppler, Regional Director
Directorate of Regulatory Operations
U. S. Atomic Energy Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137



SUBJECT: Abnormal Occurrence No. A050-331/74-119
FILE: A-118a
A-110

Dear Mr. Keppler:

In accordance with DAEC Technical Specifications, Specification 6.11.2A.1, this letter is intended as notification of an Abnormal Occurrence at the Duane Arnold Energy Center on July 16, 1974. This letter is intended to satisfy the requirement for notification by telegraph within 24 hours of the occurrence.

Identification of Occurrence

Inoperable scram discharge volume level switch, reportable in accordance with Appendix A to Operating License DPR 49, Specification 1.0.4.b. and Table 3.1-1.

Description of Occurrence

During the conduct of Surveillance Test Procedure No. 41A006 - Discharge Volume High Water Level, it was determined that level switch (LS - 1861C) was inoperative. The switch was immediately repaired and returned to operation while the reactor was in a shutdown condition.

Investigation is continuing.

A formal written report will be submitted to the Office of the Directorate of Regulatory Operations within 10 days of identification of the subject Abnormal Occurrence.

Truly yours,

G. G. Hunt, Chief Engineer
Duane Arnold Energy Center

DLW/GGH/pd

cc: John O'Leary

C. W. Sandford

J. A. Wallace

B. R. York

E. L. Hammond

H. W. Rehrauer

J. H. Gebert

D. L. Wilson

O. C. Schellberg

6673