

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 781

FILE: INCIDENT REPORT

| | | | | | | | | |
|---|------------------|-----------|------------------------|-----------------------|------------|--|-----|-------|
| FROM: Iowa Electric & Power Co. Cedar Rapids, Iowa E.L. Hammond | | | DATE OF DOC 1-17-75 | DATE REC'D 1-24-75 | LTR xxx | TWX | RPT | OTHER |
| TO: Mr. James Keppler | | | ORIG 1-signed | CC | OTHER | SENT AEC PDR <u>xxx</u> SENT LOCAL PDR <u>xxx</u> | | |
| CLASS | UNCLASS xxxxq | PROP INFO | INPUT | NO CYS REC'D 1 | | DOCKET NO: 50-331 | | |

DESCRIPTION:

Ltr reporting abnormal occurrence on 1-17-75 concerning a RHR A B pressure differential indicating switch settings.....

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Duane Arnold

FOR ACTION/INFORMATION

1-25-75 JGB

| | | | |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (S) W/ Copies | SCHWENCER (S) W/ Copies | ZIEMANN (S) W/ Copies | REGAN (E) W/ Copies |
| CLARK (S) W/ Copies | STOLZ (S) W/ Copies | DICKER (E) W/ Copies | LEAR (S) W/ Copies |
| PARR (S) W/ Copies | VASSALLO (S) W/ Copies | KNIGHTON (E) W/ Copies | SPEIS (S) W/ Copies |
| KNIEL (S) W/ Copies | PURPLE (S) W/ Copies | YOUNGBLOOD (E) W/ Copies | |

INTERNAL DISTRIBUTION

| | | | | |
|---|---|--|---|--|
| <u>REG FILE</u> AEC PDR OGC, ROOM P-506-A MUNIZING/STAFF CASE GIAMBUSSO BOYD MOORE (S) (BWR) DEYOUNG (S) (PWR) SKOVHOLT (S) GOLLER (S) P. COLLINS DENISE REG OPR FILE & REGION T.R. WILSON | <u>TECH REVIEW</u> SCHROEDER MACCARRY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA STEELE VOLIMER | <u>DENTON</u> GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS | <u>LIC. ASST.</u> DIGGS (S) GEARIN (S) GOULBOURNE (S) KREUTZER (E) LEE (S) MAIGRET (S) REED (E) SERVICE (S) SHEPPARD (S) SLATER (E) SMITH (S) TEETS (S) WILLIAMS (E) WILSON (S) INGRAM (S) | <u>A/T IND</u> BRAITMAN SALTZMAN B. HURT <u>PLANS</u> MCDONALD CHAPMAN DUBE w/input E. COUPE R. Hartfield (2) KLECKER F. WILLIAMS |
|---|---|--|---|--|

EXTERNAL DISTRIBUTION

| | | |
|--|--------------------------------|---|
| 1-LOCAL PDR Cedar Rapids, Iowa | (1) (2) (10) - NATIONAL LABS | 1-PDR SAN/LA/NY |
| 1-TIC (ABERNATHY) | 1-W. PENNINGTON, RM E-201 G.T. | 1-BROOKHAVEN NAT LAB |
| 1-NSIC (BUCHANAN) | 1-CONSULTANTS | 1-G. ULRIKSON, ORNL |
| 1-ASLB | NEWMARK/BLUME/ASBABIAN | 1-AGMED (RUTH GUSSMAN) RM B-127 G.T. |
| 1-NEWTON ANDERSON | | 1-J. RUNKLES, RM E-201 G.T. |
| 5-ACRS SENT TO LIC. ASST. <i>TEETS</i> | | |

*Telegraphed to Keppler
1-17-75 1455
E. Case*

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS IOWA
DUANE ARNOLD ENERGY CENTER



PALO, IOWA

JANUARY 17, 1975

DAEC - 75 - 21

Regulatory

File Cy.



Mr. James Keppler, Director
Regulatory Operations Regional Office
U. S. Atomic Energy Commission
79- Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: Abnormal Occurrence
FILE: A-118a
A-110

Dear Mr. Keppler:

In accordance with the DAEC Technical Specifications, Section 6.11.2A-1, this letter is intended as notification of an abnormal occurrence at the Duane Arnold Energy Center on January 17, 1975. This letter, telecopied to your office, is intended to satisfy the requirements for notification by telegram within 24 hours of an abnormal occurrence.

Identification of Occurrence

RHR A > B pressure differential indicating switch settings, reportable in accordance with Appendix A, Operating License DPR-49, Specifications 1.0.4.b and Table 3.2-B.

Description of Occurrence

During the performance of Surveillance Test Procedure No. 42B017 - RHR A7B dP Across Riser Instrument Functional Test/Calibration (LPCI Loop Selection Logic) was determined that PDIS 4644 had a trip setting of 0.2 psid.

The Technical Specification Limit is $0.5 < p < 1.5$ psid. The switch was immediately recalibrated.

1/17/75

As previously discussed with Mr. C. D. Feierabend of your office, the formal report on this abnormal occurrence will be included in the Supplemental Report for Abnormal Occurrence No.'s AO 50-331/74-48, 74-51 and 74-52.

Very truly yours,

E. L. Hammond
E. L. Hammond
Assistant Chief Engineer
Duane Arnold Energy Center

DLW:ELH:bh

CC: E. G. Case
C. W. Sandford
J. A. Wallace
G. G. Hunt
B. R. York
D. L. Wilson
R. R. Rinderman
L. D. Root
H. W. Rehrauer-Chairman, Safety Committee
G. A. Cook
B. L. Hopkins