

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 11101

FILE: _____

FROM: Iowa Electric Light & Power Cedar Rapids, Iowa CG Hunt		DATE OF DOC 10-22-74	DATE REC'D 10-29-74	LTR	TWX	RPT	OTHER FACSIMILE
TO: Mr. Keppler		ORIG NONE SIGNED	CC	OTHER	SENT AEC PDR <u>XXX</u> SENT LOCAL PDR <u>XXX</u>		
CLASS	UNCLASS XXXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-331		

DESCRIPTION:

Ltr re Abnormal occurrence #74-43 on 10-19-74
concerning intermediate range monitors

inoperable

ENCLOSURES:

DO NOT REMOVE

PLANT NAME: Duane Arnold

FOR ACTION INFORMATION

11-29-74 ehf

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u> AEC PDR EGC, ROOM P-506A MUNTZING STAFF CASE GIAMBUSO BOYD MOORE (L) (BWR) DEYOUNG (L) (PWR) SKOVHOLT (L) GOLLER (L) P. COLLINS DENISE REG OPR FILE & REGION (3) MORRIS STEELE	<u>TECH REVIEW</u> SCHROEDER ACCARY KNIGHT AWLICKI SHAO STELLO HOUSTON OVAK ROSS APPOLITO TEDESCO LONG AINAS MENAROYA WOLIMER	<u>DENTON</u> GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR <u>HARLESS</u>	<u>LIC ASST</u> DIGGS (L) GEARIN (L) GOULDSOURNE (L) KREUTZER (E) LEE (L) MAIGRET (L) REED (E) SERVICE (L) SHEPPARD (L) SLATER (E) SMITH (L) TEETS (L) WILLIAMS (E) WILSON (L)	<u>A/T IND</u> BRAITMAN SALTZMAN B. HURT <u>PLANS</u> MCDONALD CHAPMAN DUBE w/ input E. COUPE THOMPSON (2) KLECKER EISENHUT
--	--	---	--	--

EXTERNAL DISTRIBUTION


LOCAL PDR <u>Cedar Rapids, IA.</u> TIC (ABERNATHY) (1)(2)(10) - NATIONAL LAPS - NSIC (DUCHANAN) 1 - ASLB 1 - Newton Anderson ACRS HOLDING Sent to Lic Asst. <u>Teets</u>	1 - ASLB (E.W. Saly, Rm 529) 1 - W. PENNINGTON, Rm E-201 GT 1 - B&M SWINEBROOK, Rm E-201 GT 1 - CONSULTANTS NEW HARK BULL NEAGABADIAN	1 - PDR SAN/LA/NY 1 - BROOKHAVEN NAT LAB 1 - G. ULRIKSON, ORNL 1 - AGMED (BETH GUSMAN) Rm B-127 GT 1 - R. D. MUELLER, Rm E-201 GT
--	---	--

REGULATORY DOCKET FILE COPY
IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS, IOWA
DUANE ARNOLD ENERGY CENTER
PALO, IOWA

OCTOBER 22, 1974
DAEC - 74 - 364



Mr. James Keppler, Director
Regulatory Operations Regional Office
U. S. Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: Abnormal Occurrence No. DPR 50-331/74-43
FILE: A-118a A-110

Dear Mr. Keppler:

In accordance with DAEC Technical Specifications, Section 6.11.2A.1, this letter is intended as notification of an abnormal occurrence at the Duane Arnold Energy Center on October 19, 1974. This letter, telecopied to your office, is intended to satisfy the requirement for notification by telegram within 24 hours of the identification of an abnormal occurrence.

Identification of Occurrence

Intermediate Range Monitors (IRM) inoperable, reportable in accordance with Appendix A to Operating License DPR-49, Specifications 1.0.4.b and Table 3.1-1.

Description of Occurrence


While commencing a reactor startup following an inadvertent scram, it was determined that IRM instrument channels A and E (RPS Channel A) were inoperable. RPS Channel A was manually placed in the tripped condition and startup operations were suspended while the IRM's were repaired.

Investigation is continuing.

A formal written report will be submitted to the Office of Directorate of Regulatory Operations within 10 days of the identification of the subject abnormal occurrence.

Very truly yours,

G. G. Hunt
Chief Engineer
Duane Arnold Energy Center



DLW:GGH:bh

CC: E. G. Case B. R. York H. W. Rehrauer, Chairman, Safety Committee
C. W. Sandford D. L. Wilson G. A. Cook
J. A. Wallace R. R. Rinderman B. L. Hopkins
E. L. Hammond L. D. Root

11101