



— flashboard failure at 2 ft. - - - - - no flashboard failure

WLS COL 2.4-2

WILLIAM STATES LEE III
NUCLEAR STATION UNITS 1 & 2

Discharge Rating Curve, Gaston Shoals Dam

FIGURE 2.4.3-212

Rev 0