

Rio Tinto

Kennecott Uranium Company
42 Miles NW of Rawlins
P.O. Box 1500
Rawlins, WY 82301-1500
USA
T +1 (307) 328 1476
F +1 (307) 324 4925

31 August 2011

Mr. Keith I McConnell, Deputy Director

Division of Waste Management and Environmental Management Programs
Office of Federal and State Materials and Environmental Management Programs
U.S. Nuclear Regulatory Commission
11545 Rockville Pike, Mail Stop T7-E18
Rockville, Maryland 20852

Dear Mr. McConnell:

**SUBJECT: Sweetwater Uranium Project – Docket Number 40-8584
Source Material License SUA-1350 Semiannual 10 CFR 40.65 Report
Airborne Effluents – Corrected Page**


Attached please find a corrected version of the table entitled *Continuous Low-Volume Air Particulate Analysis* in the report. The units in the heading of the column entitled *Effluent Conc.* has been corrected to read uCi/ml instead of the incorrect pCi/ml. This error was discovered by James Webb of your staff in the Second Half 2010 10 CFR 40.65 Report and discussed in an e-mail dated Wednesday, April 13, 2011. Unfortunately it appeared again in the 10 CFR 40.65 Report – Airborne Effluents for the first half of 2011.

The error has now been corrected in the electronic form so that it will not occur again. In reviewing previous reports, it was observed that the error first occurred in the 10 CFR 40.65 Report – Airborne Effluents for the first half of 2003. This correction applies to all of the 10 CFR 40.65 Reports – Airborne Effluents from the one for the first half of 2003 to the one for the first half of 2011, inclusive.

Kennecott Uranium Company apologizes for the inconvenience this error has caused.

If you have any questions please do not hesitate to contact me.

Sincerely yours,



Oscar Paulson
Facility Supervisor

cc: James Webb – Project Manager
Director – USNRC DNMS, Region IV (w/o enclosure)
Rich Atkinson

STATION 4A – 2011

Day for Lead-210