

Central files

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

April 12, 1979

Mr. James G. Keppler
Director - Region III
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22
IE Bulletin No. 79-03

Extensive investigation was conducted in regard to the above referenced IE Bulletin at the Monticello Nuclear Generating Plant. It has been identified that no ASME SA-312, Type 304 or other welded (without filler metal) pipe manufactured by Youngstown Welding and Engineering Company is in use or planned for use in any safety-related systems at this facility.

If additional information is required, please communicate directly with plant management.

Yours very truly,

DE Delbert for L. J. Wachter

L. J. Wachter
Vice President
Power Production and
System Operation

cc: Mr. G. Charnoff
Office of Inspection and Enforcement
Washington, D.C.

*NOZ
LCP*

R 17 1979

7905290321