

REC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)

CONTROL NO: 13068

FILE: INCIDENT REPORT

FROM: Northern States Power Co. Minneapolis, Minn. 55401 L.J. Wachter		DATE OF DOC 12-19-74	DATE REC'D 12-27-74	LTR X	TWX	RPT	OTHER
TO: Mr. J.G. Keppler		ORIG	CC 1	OTHER	SENT AEC PDR XX SENT LOCAL PDR XX		
CLASS	UNCLASS XXXXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-263		

DESCRIPTION: Ltr submitted as a report advising that cable terminations in all safety related - 480 volt combination breaker-motor starters have been checked during the 1974 refueling stage....

ENCLOSURES:

PLANT NAME: Monticello Plant

FOR ACTION/INFORMATION

DHL 12-30-74

BUTLER (S)	SCHWENCER (S)	✓ ZIEMANN (S)	REGAN (E)
W/ Copies	W/ Copies	W/ 4 Copies	W/ Copies
CLARK (S)	STOLZ (S)	DICKER (E)	LEAR (S)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
PARR (S)	VASSALLO (S)	KNIGHTON (E)	SPEIS (S)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
KNIEL (S)	PURPLE (S)	YOUNGBLOOD (E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u>	<u>TECH REVIEW</u>	<u>DENTON</u>	<u>LIC. ASST.</u>	<u>A/T IND</u>
✓ AEC PDR	✓ SCHROEDER	GRINES	✓ DIGGS (S)	BRAITMAN
COGC, ROOM P-506-A	✓ MACCARRY	GAMMILL	GEARIN (S)	SALTZMAN
✓ MUNTZING/STAFF	✓ KNIGHT	✓ KASTNER	GOULBOURNE (S)	B. HURT
✓ CASE	✓ FAWLICKI	BALLARD	KREUTZER (E)	
GIAMBUSSO	✓ CHAO	SPANGLER	LEE (S)	<u>PLANS</u>
BOYD	✓ STELLO		MAIGRET (S)	MCDONALD
MOORE (S) (BWR)	✓ HOUSTON	<u>ENVIRO</u>	REED (E)	CHAPMAN
DEYOUNG (S) (PWR)	✓ NOVAK	MULLER	SERVICE (S)	DUBE w/input
SKOVHOLT (S)	✓ CROSS	DICKER	SHEPPARD (S)	E. COUPE
✓ GOLLER (S)	✓ IPPOLITO	KNIGHTON	SLATER (E)	✓ D. THOMPSON (2)
P. COLLINS	✓ TEDESCO	YOUNGBLOOD	SMITH (S)	✓ KLECKER
DENISE	✓ LONG	REGAN	TEETS (S)	✓ EISENHUT
<u>REG OPR</u>	✓ LAINAS	PROJECT LDR	WILLIAMS (E)	
✓ FILE & REGION	✓ BENAROYA		WILSON (S)	
✓ T.R. WILSON	✓ STEELE	HARLESS	INGRAM (S)	
	✓ VOLIMER			

EXTERNAL DISTRIBUTION


✓ 1-LOCAL PDR Minneapolis, Minn.	(1) (2) (10) -NATIONAL LABS	1-PDR SAN/LA/NY
✓ 1-TIC (ABERNATHY)	1-W. PENNINGTON, RM E-201 G.T.	1-BROOKHAVEN NAT LAB
✓ 1-NSIC (BUCHANAN)	1-CONSULTANTS	1-G. ULRIKSON, ORNL
1-ASLB	NEWMARK/BLUME/AGBABIAN	1-AGMED (RUTH GUSSMAN)
1-NEWTON ANDERSON		RM B-127 G.T.
✓ 5-ACRS SENT TO LIC. ASST.		1-J. RUNKLES, RM E-201
R. Diggs 12-30-74		G.T.



NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

December 19, 1974



Mr J G Keppler, Regional Director  
Directorate of Regulatory Operations  
Region III  
United States Atomic Energy Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 61073

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT  
Docket No. 50-263 License No. DPR-22

In accordance with DRO Bulletin No. 74-13, this report is submitted to inform you that cable terminations in all safety related 480 volt combination breaker-motor starters have been checked, in accordance with approved preventive maintenance procedures, during the 1974 refueling outage. Although the terminations were not specifically inspected for the presence of cellophane, a general inspection for tightness and continuity revealed no abnormalities, nor have there been any failures of the nature described.


Cable terminations of all safety related 480 volt combination breaker-motor starters will be again inspected, specifically for the presence of improper terminations as described, during the forthcoming refueling outage presently scheduled for January 1975. If any improper terminations are detected they will be corrected at that time and a description of the number and location of the improper terminations will be forwarded to you.

Very truly yours,

L J Wachter, Vice President  
Power Production & System Operation

LJW/ts

cc: ✓ J F O'Leary, Directorate of Licensing  
G Charnoff  
Minnesota Pollution Control Agency  
Attention: E A Pryzina



13068