

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9008010033 DOC.DATE: 90/07/25 NOTARIZED: NO DOCKET #
 FACIL:50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH.NAME AUTHOR AFFILIATION
 PARKER,T.M. Northern States Power Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards replacement Page 1.2-23 to Rev 9 to ASME Code
 Section XI insp & testing program.

DISTRIBUTION CODE: A047D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 141
 TITLE: OR Submittal: Inservice Inspection/Testing/Relief from ASME Code

NOTES:NRR/LONG,W.

05000263

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD3-1 LA		1	0		PD3-1 PD		5	5
	LONG,B.		1	1					
INTERNAL:	AEOD/DSP/TPAB		1	1		NRR/DET/ECMB 9H		1	1
	NRR/DET/EMEB 9H		1	1		NUDOCS-ABSTRACT		1	1
	OC/LEMB		1	0		OGC/HDS1		1	0
	<u>REG FILE</u> 01		1	1		RES/DSIR/EIB		1	1
EXTERNAL:	EG&G BROWN,B		1	1		EG&G RANSOME,C		1	1
	LPDR		1	1		NRC PDR		1	1
	NSIC		1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 20 ENCL 17

MAH
sub



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401-1927
Telephone (612) 330-5500

July 25, 1990

10 CFR Part 50
Section 50.55(g)

Director of Nuclear Reactor Regulation
US Nuclear Regulatory Commission
Attn: Document Control Desk
Washington DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Page Correction to the ASME Code Section XI
Inspection and Testing Program

Attached you will find Page 1.2-23 Revision 9 to the Monticello Code Section XI Inservice Inspection and Testing Program Manual. The instructions included in Revision 10 to the Monticello Code Section XI Inservice Inspection and Testing Manual called for replacement of page 1.2-23. Page 1.2-23 was not revised and was not included with the revision 10 package. Revision 10 Record of Revision is correct.

Please insure your copy of the Inservice Inspection and Testing Manual contains Page 1.2-23 Revision 9.

We are sorry for the inconvenience that this error may have caused. Please contact us if you have any question related to this page change.

Thomas M Parker
Manager
Nuclear Support Services

c: Regional Administrator-III, NRC
NRR Project Manager, NRC
NRC Resident Inspector, NRC
State of Minnesota
Hartford Insurance
G Charnoff

Attachments: Page 1.2-23 Revision 9

A047
11

9008010033 900725
PDR ADOCK 05000263
Q PDC