

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8011210450 DOC.DATE: 80/11/14 NOTARIZED: NO DOCKET #
 FACIL:50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH.NAME AUTHOR AFFILIATION
 THURMAN,P. Northern States Power Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Region 3, Chicago, Office of the Director

SUBJECT: LER 80-030/03L-0: on 801013, during normal plant operations,
 attempt to close drywell floor drain sump outboard isolation
 valve A0-2541-B failed. Caused by loss of resilience due to
 natural end life of Buna-N Diaphragm in solenoid, SV-2541-B.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL		ID CODE/NAME	LTTR
	IPPOLITO, T. 04	3	3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08	1	1	A/D OP REACT009	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	A/D TECHNOLOG13	1	1
	ACC EVAL BR 14	1	1	AEOD	2	2
	ASLBP/J.HARD	1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16	1	1	CONT SYS BR 17	1	1
	CORE PERF BR 18	1	1	D/DIR,HUM FAC19	1	1
	DIR,ENGINEER120	1	1	DIR,HUM FAC S21	1	1
	DIR,SYS INTEG22	1	1	EFF TR SYS BR23	1	1
	EQUIP QUAL BR25	1	1	GEOSCIENCES 26	1	1
	I&C SYS BR 29	1	1	I&E 05	2	2
	JORDAN,E./IE	1	1	LIC GUID BR 30	1	1
	LIC QUAL BR 31	1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33	1	1	MPA	3	3
	NRC PDR 02	1	1	OP EX EVAL BR34	3	3
	OR ASSESS BR 35	1	1	POWER SYS BR 36	1	1
	RAD ASSESS BR39	1	1	REACT SYS BR 40	1	1
	REG FILE 01	1	1	REL & RISK A 41	1	1
	SFTY PROG EVA42	1	1	STRUCT ENG BR44	1	1
	SYS INTERAC B45	1	1			
EXTERNAL:	ACRS 46	16	16	LPDR 03	1	1
	NSIC 05	1	1	TERA:DOUG MAY	1	1

CONTROL BLOCK:

						1
--	--	--	--	--	--	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	6	3	7	1	0	1	3	8	0	8	1	1	1	4	8	0	9
60	61									68	69					74		75						80

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7 8 9 FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)

1 5 E 0 9 0 NA A Electrician Observation

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION (39)						
1	7	0	0	0	(37)	Z	(38)	NA		

7	8	9	11	12	80
LOSS OF OR DAMAGE TO FACILITY (43)					
TYPE		DESCRIPTION			
1	9	Z (42)	NA		

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
		PUBLCITY		ISSUED		DESCRIPTION		NRC USE ONLY															
				(45)		NA																	

NAME OF PREPARER Patrick Thurman

68 69
612/295-5151
PHONE: _____