

# REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8105220295 DOC. DATE: 81/05/19 NOTARIZED: NO DOCKET #  
 FACIL: 50-263 Monticello Nuclear Generating Plant, Northern States 05000263  
 AUTH. NAME AUTHOR AFFILIATION  
 TOBIN, P.A. Northern States Power Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 Region 3, Chicago, Office of the Director

SUBJECT: LER 81-004/03L-0: on 810419, outbound MSIV AQ-2-86B was observed to exceed Tech Spec Table 3.7.1 required closure time. Caused by malfunction of AVC actuator. Actuator components rebuilt.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1  
 TITLE: Incident Reports

## NOTES:

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	IPPOLITO, T. 04	3	3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08	1	1	A/D OP REACT009	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	ACC EVAL BR 14	1	1
	AEOD	3	3	AEOD/DMU	3	3
	ASLBP/J. HARD	1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16	1	1	CONT SYS BR 17	1	1
	CORE PERF BR 18	1	1	DIR, ENGINEER120	1	1
	DIR, HUM FAC S21	1	1	DIR, SYS INTEG22	1	1
	EFF TR SYS BR23	1	1	EQUIP QUAL BR25	1	1
	GEOSCIENCES 26	1	1	I&C SYS BR 29	1	1
	I&E 05	1	1	JORDAN, E./IE	1	1
	LIC GUID BR 30	1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33	1	1	NRC PDR 02	1	1
	OR ASSESS BR 35	1	1	POWER SYS BR 36	1	1
	RAD ASSESS BR39	1	1	REACT SYS BR 40	1	1
	REG FILE 01	1	1	REL & RISK A 41	1	1
	SFTY PROG EVA42	1	1	STRUCT ENG BR44	1	1
EXTERNAL:	ACRS 46	16	16	LPDR 03	1	1
	NSIC 05	1	1			

MAY 27 1981

LS