

Davis-BesseNPEm Resource

From: CuadradoDeJesus, Samuel
Sent: Thursday, December 29, 2011 9:36 AM
To: dorts@firstenergycorp.com
Cc: custer@firstenergycorp.com; Davis-BesseHearingFile Resource
Subject: Telephone conference summary
Attachments: 6 29 2011 DB NRC Telecon Summary.docx; 8 22 2011 DB NRC Telecon Summary.docx
Importance: High

Steve,

Please let me know if you have any comments on the attached telephone conference summaries.

Regards,

Samuel Cuadrado de Jesús

Project Manager

Projects Branch 1

Division of License Renewal

U.S. Nuclear Regulatory Commission

Phone: 301-415-2946

Samuel.CuadradoDeJesus@nrc.gov

Hearing Identifier: Davis_BesseLicenseRenewal_Saf_NonPublic
Email Number: 3062

Mail Envelope Properties (377CB97DD54F0F4FAAC7E9FD88BCA6D0806FBBD45C)

Subject: Telephone conference summary
Sent Date: 12/29/2011 9:35:55 AM
Received Date: 12/29/2011 9:35:58 AM
From: CuadradoDeJesus, Samuel

Created By: Samuel.CuadradoDeJesus@nrc.gov

Recipients:

"custer@firstenergycorp.com" <custer@firstenergycorp.com>

Tracking Status: None

"Davis-BesseHearingFile Resource" <Davis-BesseHearingFile.Resource@nrc.gov>

Tracking Status: None

"dorts@firstenergycorp.com" <dorts@firstenergycorp.com>

Tracking Status: None

Post Office: HQCLSTR01.nrc.gov

Files	Size	Date & Time
MESSAGE	377	12/29/2011 9:35:58 AM
6 29 2011 DB NRC Telecon Summary.docx	28893	
8 22 2011 DB NRC Telecon Summary.docx	28779	

Options

Priority: High
Return Notification: No
Reply Requested: No
Sensitivity: Normal
Expiration Date:
Recipients Received:

LICENSEE: FirstEnergy Nuclear Operating Company

FACILITY: Davis-Besse

SUBJECT: SUMMARY OF TELEPHONE CONFERENCE CALL HELD ON JUNE 29, 2011 BETWEEN THE U.S. NUCLEAR REGULATORY COMMISSION AND FIRSTENERGY NUCLEAR OPERATING COMPANY, CONCERNING REQUESTS FOR ADDITIONAL INFORMATION PERTAINING TO THE DAVIS-BESSE, LICENSE RENEWAL APPLICATION (TAC. NO. ME4640)

The U.S. Nuclear Regulatory Commission (NRC or the staff) and representatives of FirstEnergy Nuclear Operating Company (FENOC or the applicant) held a telephone conference call on June 29, 2011, to discuss and clarify the applicant's responses to the staff's requests for additional information (RAIs) concerning the Davis-Besse, license renewal application.

Enclosure 1 provides a listing of the participants and Enclosure 2 contains a description of the staff concerns discussed with the applicant, a brief description on the status of the items is also included.

The applicant had an opportunity to comment on this summary.

Samuel Cuadrado de Jesús
License Renewal Branch, RPB1
Division of License Renewal
Office of Nuclear Reactor Regulation

Docket Number:50-346

Enclosures:

1. List of Participants
2. List of Requests for Additional Information

cc w/encls: See next page

LICENSEE: FirstEnergy Nuclear Operating Company

FACILITY: Davis-Besse

SUBJECT: SUMMARY OF TELEPHONE CONFERENCE CALL HELD ON JUNE 29, 2011 BETWEEN THE U.S. NUCLEAR REGULATORY COMMISSION AND FIRSTENERGY NUCLEAR OPERATING COMPANY, CONCERNING REQUESTS FOR ADDITIONAL INFORMATION PERTAINING TO THE DAVIS-BESSE, LICENSE RENEWAL APPLICATION (TAC. NO. ME4640)

The U.S. Nuclear Regulatory Commission (NRC or the staff) and representatives of FirstEnergy Nuclear Operating Company (FENOC or the applicant) held a telephone conference call on June 29, 2011, to discuss and clarify the applicant's responses to the staff's requests for additional information (RAIs) concerning the Davis-Besse, license renewal application.

Enclosure 1 provides a listing of the participants and Enclosure 2 contains a description of the staff concerns discussed with the applicant, a brief description on the status of the items is also included.

The applicant had an opportunity to comment on this summary.

Samuel Cuadrado de Jesús
License Renewal Branch, RPB1
Division of License Renewal
Office of Nuclear Reactor Regulation

Docket Number: 50-346

Enclosures:

1. List of Participants
2. List of Requests for Additional Information

cc w/encls: See next page

DISTRIBUTION: See next page

ADAMS Accession No.:

DOCUMENT NAME: Insert document name and full path.

OFFICE	LA:DLR	PM:RPB1:DLR	BC:RPB1:DLR
NAME		S Cuadrado de Jesús	D Morey
DATE	/ /	/ /	/ /

OFFICIAL RECORD COPY

TELEPHONE CONFERENCE CALL
DAVIS-BESSE
LICENSE RENEWAL APPLICATION

LIST OF PARTICIPANTS
JUNE 29, 2011

PARTICIPANTS

AFFILIATIONS

Samuel Cuadrado de Jesús	U.S. Nuclear Regulatory Commission (NRC)
Robert Sun	NRC
Elizabeth Trillo	Center for Nuclear Waste Regulatory Analyses
Cliff Custer	FirstEnergy Nuclear Operating Company (FENOC)
Steve Dort	FENOC
Kathy Nesser	FENOC
Larry Hinkle	FENOC
Allen McAllister	FENOC

REQUESTS FOR ADDITIONAL INFORMATION

LICENSE RENEWAL APPLICATION

JUNE 29, 2011

The U.S. Nuclear Regulatory Commission (NRC or the staff) and representatives of FirstEnergy Nuclear Operating Company (FENOC or the Applicant) held a telephone conference call on June 29, 2011, to discuss and clarify the following responses to requests for additional information (RAIs) concerning the license renewal application (LRA).

Response to RAI B.2.4-4

Discussion:

The NRC staff stated that LRA Tables 3.2.2-1, 3.2.2-3, 3.2.2-4, 3.3.2-5, 3.3.2-7, 3.3.2-8, 3.3.2-11, 3.3.2-14, 3.3.2-16, 3.3.2-18, 3.3.2-23, 3.3.2-24, 3.3.2-25, 3.3.2-26, 3.3.2-31, 3.4.2-1 include AMR line items for both loss of material and for cracking in stainless steel bolts exposed to air with steam or water leakage (external) managed by the Bolting Integrity Program. In these same tables, a third related AMR line item exists for loss of preload in stainless steel bolts exposed to air-indoor uncontrolled (external).

Based on the response to RAI B.2.4-4 (6/24/11), it appears that the bolts described in the 3 coupled line items are the same components, and thus all expected aging effects (Loss of material, cracking, loss of preload) are accounted for, however it is not clear as a result of the different environments listed for these line items in the LRA. If all 3 coupled line items described the same component, then why are different environments used?

Another possibility is that the 3 coupled line items describe components with some but not complete overlap, where certain bolts are managed for LOM, cracking and LOP, and others are only managed for LOP. If this were the case, then additional clarification or LRA updates would still be needed since LOM is still an expected aging effect for stainless steel bolting in an air-indoor uncontrolled (external) environment (see GALL item V.E.EP-70).

The FENOC staff explained the tables to the NRC staff by going over line items in specific tables and providing a detailed explanation of the AMR results and the subsequent AMR row assignments for stainless steel bolting. As noted by FENOC, the stainless steel bolting AMR results including the AMR row assignments are consistent with NRC guidelines. The NRC staff stated they were satisfied with the explanation.

SUBJECT: Summary of Telephone Conference Call conducted on June 29, 2011

DISTRIBUTION:

HARD COPY:

DLR RF

E-MAIL:

PUBLIC [or NON-PUBLIC, if applicable]

RidsNrrDlr Resource
RidsNrrDlrRpb1 Resource
RidsNrrDlrRpb2 Resource
RidsNrrDlrRarb Resource
RidsNrrDlrRapb Resource
RidsNrrDlrRasb Resource
RidsNrrDlrRerb Resource
RidsNrrDlrRpob Resource

PCooper
BHarris
SCuadrado
EMiller
MMahoney
ICouret, OPA
TReilly, OCA
BHarris, OGC
VMitlyng, RII
JCameron, RIII

LICENSEE: FirstEnergy Nuclear Operating Company

FACILITY: Davis-Besse

SUBJECT: SUMMARY OF TELEPHONE CONFERENCE CALL HELD ON AUGUST 22, 2011 BETWEEN THE U.S. NUCLEAR REGULATORY COMMISSION AND FIRSTENERGY NUCLEAR OPERATING COMPANY, CONCERNING REQUESTS FOR ADDITIONAL INFORMATION PERTAINING TO THE DAVIS-BESSE, LICENSE RENEWAL APPLICATION (TAC. NO. ME4640)

The U.S. Nuclear Regulatory Commission (NRC or the staff) and representatives of FirstEnergy Nuclear Operating Company (FENOC or the applicant) held a telephone conference call on August 22, 2011, to discuss and clarify the applicant's responses to the staff's requests for additional information (RAIs) concerning the Davis-Besse, license renewal application.

Enclosure 1 provides a listing of the participants and Enclosure 2 contains a description of the RAI response and concerns discussed with the applicant, a brief description on the status of the items is also included.

The applicant had an opportunity to comment on this summary.

Samuel Cuadrado de Jesús
License Renewal Branch, RPB1
Division of License Renewal
Office of Nuclear Reactor Regulation

Docket Number:50-346

Enclosures:

1. List of Participants
2. List of Requests for Additional Information

cc w/encls: See next page

LICENSEE: FirstEnergy Nuclear Operating Company

FACILITY: Davis-Besse

SUBJECT: SUMMARY OF TELEPHONE CONFERENCE CALL HELD ON AUGUST 22, 2011 BETWEEN THE U.S. NUCLEAR REGULATORY COMMISSION AND FIRSTENERGY NUCLEAR OPERATING COMPANY, CONCERNING REQUESTS FOR ADDITIONAL INFORMATION PERTAINING TO THE DAVIS-BESSE, LICENSE RENEWAL APPLICATION (TAC. NO. ME4640)

The U.S. Nuclear Regulatory Commission (NRC or the staff) and representatives of FirstEnergy Nuclear Operating Company (FENOC or the applicant) held a telephone conference call on August 22, 2011, to discuss and clarify the applicant's responses to the staff's requests for additional information (RAIs) concerning the Davis-Besse, license renewal application.

Enclosure 1 provides a listing of the participants and Enclosure 2 contains a description of the RAI response and concerns discussed with the applicant, a brief description on the status of the items is also included.

The applicant had an opportunity to comment on this summary.

Samuel Cuadrado de Jesús
License Renewal Branch, RPB1
Division of License Renewal
Office of Nuclear Reactor Regulation

Docket Number: 50-346

Enclosures:

1. List of Participants
2. List of Requests for Additional Information

cc w/encls: See next page

DISTRIBUTION: See next page

ADAMS Accession No.:

DOCUMENT NAME: Insert document name and full path.

OFFICE	LA:DLR	PM:RPB1:DLR	BC:RPB1:DLR
NAME		S Cuadrado de Jesús	D Morey
DATE	/ /	/ /	/ /

OFFICIAL RECORD COPY

TELEPHONE CONFERENCE CALL
DAVIS-BESSE
LICENSE RENEWAL APPLICATION

LIST OF PARTICIPANTS
AUGUST 22, 2011

PARTICIPANTS

AFFILIATIONS

Samuel Cuadrado de Jesús

U.S. Nuclear Regulatory Commission (NRC)

John Kloss

NRC

Cliff Custer

FirstEnergy Nuclear Operating Company (FENOC)

Steve Dort

FENOC

Kathy Nesser

FENOC

Larry Hinkle

FENOC

REQUESTS FOR ADDITIONAL INFORMATION

LICENSE RENEWAL APPLICATION

AUGUST 22, 2011

The U.S. Nuclear Regulatory Commission (NRC or the staff) and representatives of FirstEnergy Nuclear Operating Company (FENOC or the applicant) held a telephone conference call on August 22, 2011, to discuss and clarify the following response to requests for additional information (RAIs) concerning the license renewal application (LRA).

Response to RAI 3.2.2.2.3.6-2

Discussion:

LRA Table 3.2.2-2, row 20 stainless steel piping components exposed to moist air are being managed for cracking by the One-Time Inspection Program. The AMR items cite generic note H. The AMR item also cites plant-specific note 0202, which states that the One-Time Inspection is being used to confirm the absence of aging effects or that aging is slow acting so as to not affect the subject component's intended function during the period of extended operation. By letter dated May 2, 2011, the staff issued RAI 3.2.2.1.26-1 requesting that the applicant justify its use of the One-Time Inspection Program for managing these aging effects. In its response of June 3 the applicant stated that this item was deleted. However, the staff noted there was no evidence of this in the applicant letter dated May 24, 2011.

On this item there is no resolution if a proper periodic program will be used above the air water interface to manage this aging. RAI 3.2.2.2.3.6-2, was issued requesting resolution of this component in the Containment Spray System.

In its response dated August 13, 2011, the applicant did not state for Table 3.2.2-2, row 20, stainless steel piping in moist air (internal) exposed to cracking Containment Spray System, whether that item was a) retained in the One-Time Inspection program, b) documented for deletion or c) updated with an aging management program.

The staff finds the applicant's response not acceptable because the resolution concerning this line item is incomplete.

FENOC responded by stating that FENOC will provide a supplement to its response and the supplement will change the inspection from the One-Time Inspection program to the Miscellaneous Internals program. The supplemental response will be sent out by Friday, August 26, 2011. The NRC staff agreed and had no further questions.

Response to the Supplemental Response – One-Time Inspection Methods

Discussion:

The staff stated that Section A.1.30 is not in the enclosure and the teleconference in which this issue was discussed was held on 8/2/2011. The staff will like to clarify the reason why section A.1.30 wasn't amended and to clarify the date in which the teleconference was held.

FENOC stated that License Renewal Application Section A.1.30 was inadvertently listed in the response, but that Section A.1.30 did not need to be revised to include the table that was added to Section B.2.30 in the August 17, 2011, letter Enclosure. Section A.1.30 will be removed from the response and the corrected teleconference date of August 2, 2011, would be provided in a supplemental response that will be sent out by August 26, 2011. The NRC staff agreed and had no further questions.

There was no further discussion, and the call was concluded.

SUBJECT: Summary of Telephone Conference Call conducted on August 22, 2011

DISTRIBUTION:

HARD COPY:

DLR RF

E-MAIL:

PUBLIC [or NON-PUBLIC, if applicable]

RidsNrrDlr Resource
RidsNrrDlrRpb1 Resource
RidsNrrDlrRpb2 Resource
RidsNrrDlrRarb Resource
RidsNrrDlrRapb Resource
RidsNrrDlrRasb Resource
RidsNrrDlrRerb Resource
RidsNrrDlrRpob Resource

PCooper
BHarris
SCuadrado
EMiller
MMahoney
ICouret, OPA
TReilly, OCA
BHarris, OGC
VMitlyng, RII
JCameron, RIII

DWrona