

February 24, 2012

Dr. K. Jordan
Director of Nuclear Facilities
Nuclear and Radiological Engineering Department
P. O. Box 11830
University of Florida
Gainesville, FL 32611

SUBJECT: UNIVERSITY OF FLORIDA TEST REACTOR - NRC SECURITY INSPECTION
REPORT NO. 50-083/2012-202

Dear Dr. Jordan:

The U.S. Nuclear Regulatory Commission (NRC, the Commission) conducted a routine announced security inspection on January 30, 2012 thru February 3, 2012, at your University of Florida Test Reactor facility (Inspection Report No. 50-083/2012-202). The enclosed report documents the inspection results, which were discussed on February 3, 2012, with you and other members of your staff.

The inspection examined activities conducted under your license as they relate to security and compliance with the Commission's rules and regulations, implementation of certain compensatory measures, and compliance with the conditions of your license. The inspector reviewed selected procedures and records, observed activities, and interviewed personnel. Based on the results of this inspection, no findings of significance were identified. No response to this letter is required.

In accordance with Title 10 of the *Code of Federal Regulations* Section 2.390, "Public inspections, exemptions, and requests for withholding," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (Agencywide Documents Access and Management System (ADAMS)). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related items contained in the enclosure, and in accordance with 10 CFR 2.390(d), a copy of the enclosure will not be available for public inspection. Should you have any questions concerning this inspection, please contact Jack Donohue at 301-452-1950 or electronic mail at Jack.Donohue@nrc.gov.

Sincerely,
/RA/

Johnny H. Eads, Jr., Chief
Research and Test Reactors Oversight Branch
Division of Policy and Rulemaking
Office of Nuclear Reactor Regulation

Docket No. 50-083
License No. R-56

Enclosure: NRC Security Inspection Report
No. 50-083/2012-202
cc: w/o encl: See next page

NOTICE: The attachment contains Security-Related Information. Upon separation of the attachment, this letter and enclosure are DECONTROLLED.

University of Florida

Docket No. 50-83

cc:

Dr. David Hintenlang, Chairman
Nuclear & Radiological Engineering Department
University of Florida
202 Nuclear Sciences Center
PO Box 118300
Gainesville, FL 32601-8300

Administrator
Department of Environmental Regulation
Power Plant of Siting Section
State of Florida
2600 Blair Stone Road
Tallahassee, FL 32301

State Planning and Development Clearinghouse
Office of Planning and Budgeting
Executive Office of the Governor
The Capitol Building
Tallahassee, FL 32301

Chief, Bureau of Radiation Control
Department of Health
4052 Bald Cypress Way
Tallahassee, FL 32399-1741

Test, Research and Training
Reactor Newsletter
Director of Nuclear Facilities
University of Florida
202 Nuclear Science Building
Gainesville, FL 32611-8300

Brian Shea, Reactor Manager
University of Florida
Nuclear & Radiological Engineering Dept
202 Nuclear Sciences Center
P.O. Box 118300
Gainesville, FL 32611-8300

Dean Cammy Abernathy
University of Florida College of Engineering
PO Box 116550
Gainesville, FL 32611

February 24, 2012

Dr. K. Jordan
Director of Nuclear Facilities
Nuclear and Radiological Engineering Department
P. O. Box 11830
University of Florida
Gainesville, FL 32611

SUBJECT: UNIVERSITY OF FLORIDA TEST REACTOR - NRC SECURITY INSPECTION
REPORT NO. 50-083/2010-202

Dear Dr. K. Jordan:

On January 30 - February 3, 2012, the U.S. Nuclear Regulatory Commission (NRC, the Commission) conducted a routine security inspection at your University of Florida Test Reactor facility (Inspection Report No. 50-083/2012-202). The enclosed report documents the inspection results, which were discussed on February 3, 2012, with you and other members of your staff.

The inspection examined activities conducted under your license as they relate to security and compliance with the Commission's rules and regulations, implementation of certain compensatory measures, and compliance with the conditions of your license. The inspector reviewed selected procedures and records, observed activities, and interviewed personnel. Based on the results of this inspection, no findings of significance were identified. No response to this letter is required.

In accordance with Title 10 of the *Code of Federal Regulations* Section 2.390, "Public inspections, exemptions, and requests for withholding," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (Agencywide Documents Access and Management System (ADAMS)). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related items contained in the enclosure, and in accordance with 10 CFR 2.390(d), a copy of the enclosure will not be available for public inspection. Should you have any questions concerning this inspection, please contact Jack Donohue at 301-452-1950 or electronic mail at Jack.Donohue@nrc.gov.

Sincerely,

/RA/

Johnny H. Eads, Jr., Chief
Research and Test Reactors Oversight Branch
Division of Policy and Rulemaking
Office of Nuclear Reactor Regulation

Docket No. 50-083
License No. R-56

Enclosure: NRC Security Inspection Report
No. 50-083/2012-202

cc: w/o encl: See next page

DISTRIBUTION (w/o encl.):

PUBLIC PROBr/f	RidsNrrDprPrta	RidsNrrDprPrtb	JDonohue, NRR
RidsOgcMailCenter	MCompton (cover letter only)(O5-A4)	GLappert, NRR	
DHardesty, NRR	TLichatz, NRR		

ADAMS Package No.: ML120540010, Cvr Letter: ML120540011, Enclosure: ML120540012 TEMPLATE #: NRC-002

OFFICE	PROB:RI	PRPB:LA	PROB:BC
NAME	JDonohue	GLappert	JEads
DATE	2/ 22 / 2012	2/ 23 / 2012	2/24/2012

OFFICIAL RECORD COPY

NOTICE: The attachment contains Security-Related Information. Upon separation of the attachment, this letter and enclosure are DECONTROLLED.