


**Comanche Peak Nuclear Power Plant, Units 3 & 4**  
**COL Application**  
**Part 2, FSAR**



Notes:

1. Uniaxial stress for UC and PLI tests and deviator stress for CU and UU tests

**Figure 2.5.4-227 Compressive Strength vs. Elevation**