

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8910030192 DOC.DATE: 89/09/14 NOTARIZED: NO DOCKET #
 FACIL:50-361 San Onofre Nuclear Station, Unit 2, Southern Californ 05000361
 50-362 San Onofre Nuclear Station, Unit 3, Southern Californ 05000362
 AUTH.NAME AUTHOR AFFILIATION
 NANDY,F.R. Southern California Edison Co.
 RECIP.NAME RECIPIENT AFFILIATION
 MARTIN,J.B. Region 5, Ofc of the Director

SUBJECT: RO:during Aug 1989,inoperable fire doors.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1 1	PD5 PD	1 1
	HICKMAN,D	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	ACRS WYLIE	1 1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	NRR/DEST/CEB 8H	1 1
	NRR/DEST/ESB 8D	1 1	NRR/DEST/ICSB 7	1 1
	NRR/DEST/MEB 9H	1 1	NRR/DEST/MTB 9H	1 1
	NRR/DEST/PSB 8D	1 1	NRR/DEST/RSB 8E	1 1
	NRR/DEST/SGB 8D	1 1	NRR/DLPQ/HFB 10	1 1
	NRR/DLPQ/PEB 10	1 1	NRR/DOEA/EAB 11	1 1
	NRR/DREP/RPB 10	2 2	NUDOCS-ABSTRACT	1 1
	REG FILE 02	1 1	RES/DSIR/EIB	1 1
	RGN5 FILE 01	1 1		
EXTERNAL:	EG&G WILLIAMS,S	4 4	L ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC MAYS,G	1 1	NSIC MURPHY,G.A	1 1
	NUDOCS FULL TXT	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 39 ENCL 39

10-4

Southern California Edison Company

P. O. BOX 800

2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

F. R. NANDY
MANAGER OF NUCLEAR LICENSING

September 14, 1989

TELEPHONE
(818) 302-1896

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Gentlemen:

Subject: Docket Nos. 50-361 and 50-362
Followup Report, Inoperable Fire Doors - August 1989
San Onofre Nuclear Generating Station, Units 2 and 3

The purpose of this letter is to provide a follow-up report for Technical Specification fire-rated assemblies (specifically fire doors) found inoperable during routine surveillances in August 1989. This monthly report and previous monthly reports provide updated information associated with the initial 1983 report.

The attachment to this letter identifies fire doors found inoperable during the August routine surveillances and consists of: 11 latching mechanism failures and 3 closure mechanism failures. As each of these deficiencies was identified, compensatory fire watches were established pursuant to Technical Specification 3.7.9, Action Statement "a". No doors were found to be blocked open in August.

If you require any additional information, please advise.


Very truly yours,



Enclosure

cc: C. W. Caldwell (NRC Senior Resident Inspector, Units 1, 2 and 3)
U. S. Nuclear Regulatory Commission Document Control Desk
Institute of Nuclear Power Operations (INPO)

8910030192 890914
PDR ADOCK 05000361
S PDC

IE22
11


ATTACHMENT
SOUTHERN CALIFORNIA EDISON COMPANY
INOPERABLE FIRE DOORS FOR THE MONTH OF AUGUST 1989
SAN ONOFRE NUCLEAR GENERATING STATION
UNITS 2 AND 3, DOCKET NOS. 50-361 and 50-362

I. Latching Mechanism Failures:

Number of doors inoperable - 11, as follows:

<u>Door Number</u>	<u>Inoperable</u>	<u>Operable</u>
AC-105	06/22/89	- - -
AC-428	06/27/89	- - -
FH2-101	07/22/89	- - -
FH3-103	07/22/89	- - -
FH3-404	07/25/89	- - -
AC-223	08/04/89	08/08/89
AC-242	08/14/89	- - -
DG3-104	08/14/89	- - -
AC-108	08/16/89	- - -
FH2-403	08/16/89	- - -
AC-310	08/20/89	- - -

II. Closure Mechanism Failures:

Number of doors inoperable - 3, as follows:

<u>Door Number</u>	<u>Inoperable</u>	<u>Operable</u>
AC-119	04/30/89	- - -
AC-108	08/16/89	- - -
C3-406	08/31/89	- - -

III. Doors Blocked Open:

Number of doors blocked open - None