



RECEIVED
NRC

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

1985 SEP 16 AM 10:46

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. E. MORGAN
STATION MANAGER

REGION V IAE

TELEPHONE
(714) 368-6241

September 10, 1985

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket Nos. 50-361 and 50-362
Follow-up Report, Inoperable Fire Doors - August 1985
San Onofre Nuclear Generating Station, Units 2 and 3

Reference: Letter, H. E. Morgan (SCE) to J. B. Martin (NRC),
dated August 13, 1985

In accordance with our referenced letter, this submittal provides the follow-up report of fire-rated assemblies (specifically fire doors) found inoperable during routine surveillances in August 1985.

Fire doors found inoperable during the August routine surveillances are identified in the Attachment and include: 7 latching mechanism failures; 2 closure mechanism failures; and 3 doors blocked open typically for construction, operation or maintenance activities. As each of these deficiencies was identified, compensatory fire watches, pursuant to Technical Specification 3.7.9, Action Statement 'a', were established. We are continuing previously reported corrective actions to upgrade door latches and closure mechanisms.

In accordance with Station practice, investigations were conducted for the 3 fire doors found blocked open. The responsible party was identified for all 3 doors found blocked open and appropriate actions will be taken.

This monthly follow-up report and those sent previously provide updated information associated with an ongoing condition initially reported in 1983. The follow-up report covering inoperable fire doors identified in September 1985 will be submitted by October 15, 1985.

8509270083 850910
PDR ADOCK 05000361
S PDR

IE-01

Mr. J. B. Martin

-2-

If you require any additional information, please so advise.

Sincerely,

A handwritten signature in dark ink, appearing to read "H. E. Mose", followed by a horizontal line extending to the right.

Enclosure

cc: F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)

U. S. Nuclear Regulatory Commission
Document Control Desk

Institute of Nuclear Power Operations (INPO)

ATTACHMENT
SOUTHERN CALIFORNIA EDISON COMPANY
INOPERABLE FIRE DOORS FOR THE MONTH OF AUGUST 1985
SAN ONOFRE NUCLEAR GENERATING STATION
UNITS 2 AND 3, DOCKET NOS. 50-361 and 50-362

I. Latching Mechanism Failures:

Number of doors inoperable - 7, as follows:

<u>Door Number</u>	<u>Inoperable</u>	<u>Operable</u>
AR-401	7/29/85	8/3/85
AC-236	8/10/85	8/13/85
AC-122	8/11/85	- - -
DG2-103	8/11/85	8/14/85
AC-416	8/15/85	- - -
AC-415	8/16/85	- - -
AC-236	8/17/85	8/18/85

ATTACHMENT
SOUTHERN CALIFORNIA EDISON COMPANY
INOPERABLE FIRE DOORS FOR THE MONTH OF AUGUST 1985
SAN ONOFRE NUCLEAR GENERATING STATION
UNITS 2 AND 3, DOCKET NOS. 50-361 and 50-362
(Continued)

II. Closure Mechanism Failures:

Number of doors inoperable - 2, as follows:

<u>Door Number</u>	<u>Inoperable</u>	<u>Operable</u>
FH3-304	8/23/85	8/24/85
FH3-304	8/31/85	---

ATTACHMENT
SOUTHERN CALIFORNIA EDISON COMPANY
INOPERABLE FIRE DOORS FOR THE MONTH OF AUGUST 1985
SAN ONOFRE NUCLEAR GENERATING STATION
UNITS 2 AND 3, DOCKET NOS. 50-361 and 50-362
(Continued)

III. Doors Blocked Open:

Number of doors blocked open - 3, as follows:

<u>Door Number</u>	<u>Date Found Blocked Open *</u>
S3-018	8/1/85
AR-204	8/4/85
AR-204	8/10/85

* (fire watches established within one hour)