

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7903060458 DOC. DATE: 79/02/22 NOTARIZED: NO DOCKET #
 FACIL: 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2, SOUTHERN CALIFORN 05000361
 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3, SOUTHERN CALIFORN 05000362
 AUTH. NAME AUTHOR AFFILIATION
 MOORE, J.B. SOUTHERN CALIFORNIA EDISON CO.
 RECIP. NAME RECIPIENT AFFILIATION
 ENGELKEN, R.H. REGION 5, SAN FRANCISCO, OFFICE OF THE DIRECTOR

SUBJECT: FORWARDS DEFICIENCY REPT RE SURFACED DEFECTS IN CARBON STEEL PIPE.

DISTRIBUTION CODE: 50195 COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+2
 TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).

NOTES: SEND ALL FSAR + ER AMOTS TO L. CHANDLER.

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	14 PM ROOD	1 1	15 BC LWR#2	1 1
	20 LA LWR#2	1 1	21 AD VASSALLO	1 1
INTERNAL:	01 REG FILE	1 1	02 NRC PDR	1 1
	05 ISE	2 2	07 EDO & STAFF	1 1
	08 MPA	1 1	09 DEPY DIR DPM	1 1
	10 QAB	1 1	11 STANDARDS DEV	1 1
	12 JORDAN, E/IE	1 1	13 FIELD COOR/IE	1 1
	16 AD FOR ENGR	1 1	17 AD PLANT SYS	1 1
	17 AD REAC SFTY	1 1	19 AD SYS/PROJ	1 1
	22 DIR DPM	1 1	23 OELD	1 1
EXTERNAL:	03 LPDR	1 1	04 NSIC	1 1
	24 ACRS	16 16		

MAR 7 1979

MA 1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 39 ENCL 39

GD

Southern California Edison Company

P. O. BOX 800

2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

JACK B. MOORE
VICE PRESIDENT

February 22, 1979

TELEPHONE
213-572-2292

Mr. R. H. Engelken, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 North California Blvd.
Walnut Creek, CA 94596


Dear Mr. Engelken:

Subject: Docket Nos. 50-361 and 50-362
San Onofre Nuclear Generating Station, Units 2 and 3

By letter dated January 23, 1979, we confirmed notification concerning a reportable condition in construction of San Onofre Units 2 and 3 related to surface defects in carbon steel pipe manufactured by Taylor Forge. Enclosed, in accordance with 10CFR50.55(e), are twenty five (25) copies of an interim report concerning this matter entitled, "Interim Report on Taylor Forge Pipe Defects, San Onofre Nuclear Generating Station, Units 2 and 3." By April 6, 1979, we will advise you of the submittal date for the final report.

If you have any questions regarding this report, we would be pleased to discuss this matter with you at your convenience.

Sincerely,



Enclosure

cc: John Davis (NRC-Acting Director I&E) ✓
R. J. Pate (NRC-San Onofre Units 2 and 3)

REGULATORY DOCKET FILE COPY

Boia
S/1

7903060458