

Southern California Edison Company


P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

D. E. NUNN
MANAGER, QUALITY ASSURANCE

TELEPHONE
(213) 572-1695

June 15, 1979

Mr. R. H. Engelken, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 North California Boulevard
Walnut Creek, California 94596



Dear Mr. Engelken:

Subject: Docket Nos. 50-361 and 50-362
San Onofre Nuclear Generating Station, Units 2 and 3

In a letter to your office dated May 18, 1979 we forwarded copies of the final 10CFR50.55(e) report entitled "Undersized Safety Related HVAC Damper Actuators, San Onofre Nuclear Generating Station, Units 2 and 3." In a telephone conversation on June 6, 1979 between R. T. Dodds of your office and Jack B. Moore, SCE Vice President and in subsequent discussions on June 13, 1979 with R. J. Pate, Resident NRC Inspector, it was agreed that the final report forwarded by our May 18, 1979 letter would be supplemented to discuss the generic implications of the deficiency described in the report.

This supplemental information will be provided to you by July 27, 1979. If you have any questions, or require additional information please let me know.

Very truly yours,

A handwritten signature in dark ink, appearing to read "R. J. Pate", written over a horizontal line.

cc: R. J. Pate (NRC, San Onofre Units 2 and 3)
Jack B. Moore

7907100654

79-96