

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7908010577 DUC. DATE: 79/07/27 NOTARIZED: NO DOCKET #
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern California 05000361
 50-362 San Onofre Nuclear Station, Unit 3, Southern California 05000362
 AUTH. NAME AUTHOR AFFILIATION
 MOORE, J.B. Southern California Edison Co.
 RECIP. NAME RECIPIENT AFFILIATION
 ENGELKEN, R.H. Region 5, San Francisco, Office of the Director

SUBJECT: Forwards suppl to final deficiency rept re undersized
 safety related HVAC damper actuators.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+3
 TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).

NOTES: 1. send all FSAR + ER AMEND to L. CHANDLER

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	14 PM R00D	1 1	15 BC LWR#2	1 1
	20 LA LWR#2	1 1	21 AD VASSALLO	1 1
INTERNAL:	01 REG FILE	1 1	02 NRC PDR	1 1
	05 I&E	2 2	07 EDO & STAFF	1 1
	08 MPA	1 1	09 DEPY DTR DPM	1 1
	10 QAB	1 1	11 STANDRDS DEV	1 1
	12 JORDAN, E/IE	1 1	13 FIELD COOR/IE	1 1
	16 AD FOR ENGR	1 1	17 AD PLANT SYS	1 1
	17 AD REAC SFTY	1 1	19 AD SYS/PROJ	1 1
	22 DIR DPM	1 1	23 OELD	1 1
	AD/SITE TECH	1 1	DIRECTOR DSE	1 1
	GEOSCIENCES BR	1 1	STRUCT ANALYS BR	1 1
EXTERNAL:	03 LPDR	1 1	04 NSIC	1 1
	24 ACRS	16 16		

AUG 3 1979

TOTAL NUMBER OF COPIES REQUIRED: LTTR 43 ENCL 43

MA 1
 61

Southern California Edison Company

SE

P. O. BOX 800

2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

JACK B. MOORE
VICE PRESIDENT

TELEPHONE
213-572-2292

July 27, 1979

Mr. R. H. Engelken, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 North California Boulevard
Walnut Creek, California 94596

REGULATORY DOCKET FILE COPY

Dear Mr. Engelken:


Subject: Docket Nos. 50-361 and 50-362
San Onofre Nuclear Generating Station, Units 2 and 3

By letter dated June 15, 1979, we advised you that supplemental information was being developed pursuant to discussions with your staff regarding the final 10CFR50.55(e) Report entitled, "Undersized Safety Related HVAC Damper Actuators, San Onofre Nuclear Generating Station, Units 2 and 3."

Enclosed in accordance with 10CFR50.55(e) are twenty-five (25) copies of a supplement to our final report submitted on May 18, 1979 entitled, "Supplemental Report - Undersized Safety Related HVAC Damper Actuators, San Onofre Nuclear Generating Station, Units 2 and 3."

If you have any questions regarding this report, we would be pleased to discuss this matter with you at your convenience.

Very truly yours,



Enclosures

cc: Victor Stello (NRC, Director I&E)
R. J. Pate (NRC, San Onofre Units 2 and 3)

3019
S
11

7908010577 S