

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8404300126 DOC. DATE: 84/04/26 NOTARIZED: NO DOCKET #
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern Californ 05000361
 50-362 San Onofre Nuclear Station, Unit 3, Southern Californ 05000362
 AUTH. NAME: AUTHOR AFFILIATION
 MEDFORD, M.O. Southern California Edison Co.
 RECIP. NAME: RECIPIENT AFFILIATION
 KNIGHTON, G.W. Licensing Branch 3

SUBJECT: Forwards auxiliary feedwater sys monthly outage rept for
 840216-0315.

DISTRIBUTION CODE: B001S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: Licensing Submittal: PSAR/FSAR Amdts & Related Correspondence

NOTES: J Hanchett 1cy PDR Documents, ELD Chandler 1cy. 05000361
 J Hanchett 1cy PDR Documents, ELD Chandler 1cy. 05000362

RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
	LTTR	ENCL		LTTR	ENCL
NRR/DL/ADL	1	0	NRR LB3 BC	1	0
NRR LB3 LA	1	0	ROOD, H. 01	1	1
INTERNAL: ELD/HDS2	1	0	IE FILE	1	1
IE/DEPER/EPB 36	3	3	IE/DEPER/IRB 35	1	1
IE/DQASIP/QAB21	1	1	NRR/DE/AEAB	1	0
NRR/DE/CEB 11	1	1	NRR/DE/EHEB	1	1
NRR/DE/eqb 13	2	2	NRR/DE/GB 28	2	2
NRR/DE/MEB 18	1	1	NRR/DE/MTEB 17	1	1
NRR/DE/SAB 24	1	1	NRR/DE/SGEB 25	1	1
NRR/DHFS/HFEB40	1	1	NRR/DHFS/LQB 32	1	1
NRR/DHFS/PSRB	1	1	NRR/DL/SSPB	1	0
NRR/DSI/AEB 26	1	1	NRR/DSI/ASB	1	1
NRR/DSI/CPB 10	1	1	NRR/DSI/CSB 09	1	1
NRR/DSI/ICSB 16	1	1	NRR/DSI/METB 12	1	1
NRR/DSI/PSB 19	1	1	NRR/DSI/RAB 22	1	1
NRR/DSI/RSB 23	1	1	<u>REG FILE</u> 04	1	1
RGNS	3	3	RM/DDAMI/MIB	1	0

EXTERNAL: ACRS 41	6	6	BNL (AMDTS ONLY)	1	1
DMB/DSS (AMDTS)	1	1	FEMA-REP DIV 39	1	1
LPDR 03	1	1	NRC PDR 02	1	1
NSIC 05	1	1	NTIS	1	1

NOTES: 2 2

Southern California Edison Company



P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770
April 26, 1984

M.O. MEDFORD
MANAGER, NUCLEAR LICENSING

TELEPHONE
(213) 572-1749

Director, Office of Nuclear Reactor Regulation
Attention: Mr. George W. Knighton, Branch Chief
Licensing Branch No. 3
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Gentlemen:

Subject: Docket Nos. 50-361 and 50-362
Auxiliary Feedwater System Monthly Outage Report
San Onofre Nuclear Generating Station, Units 2 and 3

Pursuant to License Condition 2.C(26) of Facility Operating License NPF-15 for San Onofre Unit 3, this submittal provides the required monthly report describing any occurrence resulting in the degradation of the Units 2 and 3 Auxiliary Feedwater Systems (AFWS). This report covers the period from February 16, 1984, to March 15, 1984, and also includes an outage on February 8, 1984, which was omitted from last month's report. The component involved, cause of outage, and corrective actions taken to return the equipment to operable status are listed. The durations of the Units 2 and 3 equipment outages are not specified, since both Units were in Modes 4 or 5 during the equipment outages, and the AFWS was not required to be operable per Technical Specifications.

In accordance with License Condition 2.C(26), our next report will cover the period from March 16, 1984, to April 15, 1984.

If there are any questions regarding this report, please contact me.

Sincerely,

Enclosure

cc: J. B. Martin, (Regional Administrator
U.S. Nuclear Regulatory Commission, Region V)

H. Rood, Project Manager, SONGS 2/3, NRR

A. E. Chaffee (USNRC Resident Inspector, Units 1, 2 and 3)
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

8404300126 840426
PDR ADOCK 05000361
R PDR

13001
11

Monthly AFWS Outage Report
February 16, 1984 to March 15, 1984

Date	Unit	Outage	Duration (hours)	Outage Cause	Corrective Action
2/08/84	3	Corrective Maintenance	--	Plug next to discharge flange on S31305MP140 leaked.	Cleaned, lubed and reinstalled plug.
2/20/84	3	Corrective Maintenance	--	3HV4731 would not operate.	Installed new valve motor.
2/25/84	3	Corrective Maintenance	--	Accumulator for 3HV4714 was losing pressure due to an internal leak in pressure gauge.	Installed a new accumulator.
3/02/84	3	Preventive Maintenance	--	3HV4714 was taken out of service to change oil and filter.	None required.