

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8507160364 DOC. DATE: 85/07/12 NOTARIZED: NO DOCKET #
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern California 05000361
 50-362 San Onofre Nuclear Station, Unit 3, Southern California 05000362
 AUTH. NAME AUTHOR AFFILIATION
 MEDFORD, M.O. Southern California Edison Co.
 RECIP. NAME RECIPIENT AFFILIATION
 KNIGHTON, G.W. Licensing Branch 3

SUBJECT: Provides auxiliary feedwater sys monthly rept for
 850516-0615. Units 2 & 3 operated in Mode 3 & above during
 entire reporting period w/100% auxiliary feedwater sys
 availability.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: OR Submittal: General Distribution

NOTES: ELD Chandler 1cy. 05000361
 OL: 02/16/82
 ELD Chandler 1cy. 05000362
 OL: 11/15/82

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
NRR LB3 BC 01	7 7		

INTERNAL: ACRS 09	6 6	ADM/LFMB	1 0
ELD/HDS2	1 0	NRR/DE/MTEB	1 1
NRR/DL DIR	1 1	NRR/DL/ORAB	1 0
NRR/DL/TSRG	1 1	NRR/DSI/METB	1 1
NRR/DSI/RAB	1 1	REG FILE 04	1 1
RGNS	1 1		

EXTERNAL: 24X	1 1	EG&G BRUSKE, S	1 1
LPDR 03	1 1	NRC PDR 02	1 1
NSIC 05	1 1		

NOTES: 1 1

Southern California Edison Company



P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

M. O. MEDFORD
MANAGER, NUCLEAR LICENSING

July 12, 1985

TELEPHONE
(818) 302-1749

Director, Office of Nuclear Reactor Regulation
Attention: Mr. George W. Knighton, Branch Chief
Licensing Branch No. 3
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Gentlemen:

Subject: Docket Nos. 50-361 and 50-362
Auxiliary Feedwater System Monthly Outage Report
San Onofre Nuclear Generating Station, Units 2 and 3

Pursuant to License Condition 2.C(26) of Facility Operating License NPF-15 for San Onofre Unit 3, this submittal provides the required monthly report describing any occurrence resulting in the degradation of the Units 2 and 3 Auxiliary Feedwater Systems (AFWS). This report covers the period from May 16, 1985 to June 15, 1985. The component involved, cause of outage, outage duration, and corrective actions taken to return the equipment to operable status are listed.

Units 2 and 3 operated in Mode 3 and above during the entire reporting period, with 100% AFWS availability. Unit 2 had a 3% component unavailability and Unit 3 had a 2% component unavailability.

In accordance with License Condition 2.C(26), our next report will cover the period from June 16, 1985 to July 15, 1985.

If there are any questions regarding this report, please contact me.

Sincerely,

Enclosure

cc: J. B. Martin (Regional Administrator,
U.S. Nuclear Regulatory Commission, Region V)
H. Rood (Project Manager, SONGS 2/3,
U.S. Nuclear Regulatory Commission, NRC)

F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

8507160364 850712
PDR ADOCK 05000361
R PDR

Acc'd
1/1

San Onofre Nuclear Generating Station, Units 2 and 3
Monthly AFWS Outage Report
June 16, 1985 to July 15, 1985

Date	Unit	Outage	Duration (hours)	Outage Cause	Corrective Action
5/16/85	2	Corrective Maintenance	24.75	Steam Generator E088 Auxiliary Feedwater Isolation Valve 2HV4730 removed from service to investigate spurious breaker trips. (This is a continuation of condition reported on June 17, 1985 report)	Found burnt wire in valve operator. Repaired wire and returned valve to service.
5/24/85	3	Corrective Maintenance	19.75	Auxiliary Feedwater Control Valve 3HV4706 removed from service to investigate spurious breaker trip.	Found space heater grounded. Replaced heater and returned valve to service.