



Southern California Edison Company

P. O. BOX 800

2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

M. O. MEDFORD
MANAGER, NUCLEAR LICENSING

TELEPHONE
(818) 302-1749

July 2, 1986

Director of Nuclear Reactor Regulation
Attention: G. E. Lear, Director
Project Directorate No. 1
Division of PWR Licensing - A
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Gentlemen:

Subject: Docket No. 50-206
Implementation of Generic Requirements
San Onofre Nuclear Generating Station
Unit 1

Your letter dated April 30, 1986 requested that we assist you in providing information for the Regulatory Information Tracking System. In the enclosed we have provided the status of the issues and the dates of completion or scheduled completion. For those issues where Licensee Status and Date has not been provided, additional information is needed from the NRC Project Manager to better define the issue such that a status can be provided.

If you have any questions regarding the enclosure, please let me know.

Very truly yours,

Enclosure

8607080195 860702
PDR ADOCK 05000206
P PDR

REGULATORY INFORMATION TRACKING SYSTEM

FACILITY IMPLEMENTATION

FACILITY: SAN ONOFRE 1

PLANT LOCATION: 5 MI S OF SAN CLEMENTE,
 DOCKET NUMBER: 050-00206
 ARCH/ENGINEER: BECH
 IE INSPECTOR: A. DANGELO

LICENSED POWER: 1347 MWT
 DESIGN POWER: 0436 MWE
 NSSS VENDOR: WEST

PROJECT MANAGER: R. DUDLEY
 BRANCH CHIEF: G. LEAR
 LIC. ASSISTANT: P. SHUTTLEWORTH

TAC NO.	MPA #	TITLE	LIC ACT COMPLETE	STATUS	LICENSEE	DATE
M07099	A-01	10 CFR 50.55 A(G) - ISI	09/26/79C	1978 Program in effect; update scheduled for 1989		
M08101	A-02	APPENDIX I - ALARA	08/27/84C	1/1/85 T.S. Effective; Mods completed by RTS 6/86		
M07079	A-03	SECURITY REVIEWS-MODIFIED AMENDMENT PLANS	04/10/79C	Revision 9 under NRC Review		SCE letter 5/8/86
M08592	A-04	APPENDIX J - CONTAINMENT LEAK TESTING	08/03/82C	TS issued 6/4/84 and 2/8/85; additional info on leakage criteria to be submitted		
M08448	A-06	RESPIRATORY PROTECTION SYSTEM	11/27/78C	Completed		NRC Letter 11/27/78
M10153	A-09	PRESSURE VESSEL BELTLINE MATERIAL SURVEILLANCE	01/11/81C	Capsule scheduled to be removed		1988 Refueling outage
M10588	A-10	CONTINGENCY PLANNING	01/22/81C	Revision 1A approved		NRC letter 9/6/85
M10587	A-11	GUARD TRAINING PLANS	01/22/81C	Revision 4 approved		NRC letter 1/14/86
M10584	A-12	VITAL AREA ANALYSIS	04/12/82C			
M11231	A-14	10 CFR 50.55 A(G) - INSERVICE TESTING	04/01/86C	IST program in effect; SCE letter 3/3/86 under NRC review		
M12557	A-15	QUALITY ASSURANCE REQUEST REGARDING DIESEL GENERATOR	04/14/80C			
M51130	A-17	INSTRUMENTATION TO FOLLOW THE COURSE OF AN ACCIDENT	09/30/86	Under NRC review		SCE letter 12/16/85
M59138	A-20	10 CFR 50.62 OPERATING REACTOR REVIEWS	09/30/86	Modifications to be implemented in accordance with ILS		
M59980	A-21	10 CFR 50.61, PRESSURIZED THERMAL SHOCK RULE	07/31/86	Analysis completed		SCE submittal 1/23/86
M06766	B-02	FIRE PROTECTION	07/19/79C	To be completed by RTS		6/86
M08399	B-03	PWR MODERATOR DILUTION	02/21/79C	Completed with TS issuance		NRC SER 4/23/84
M06836	B-04	REACTOR VESSEL OVERPRESSURE PROTECTION	10/27/82C	System completed; T.S. Under NRC Review		SCE letter 1/21/86
M07808	B-07	STEAM GENERATOR FEEDWATER FLOW INSTABILITY	01/20/81C			
M07849	B-09	CHARGING SYSTEMS PIPE VIBRATIONS	09/25/79C	Completed evaluation 4/20/79		NRC letter 9/25/79
M07966	B-11	FLOOD OF EQUIPMENT IMPORTANT TO SAFETY	03/18/81C	Bellows sleeve completed; CST Analysis completed 5/19/86		

REGULATORY INFORMATION TRACKING SYSTEM

FACILITY IMPLEMENTATION

FACILITY: SAN ONOFRE 1 (CONTINUATION)

TAC NO.	MPA #	TITLE	LIC ACT COMPLETE	STATUS	LICENSEE	DATE
M06492	B-12	STEAM GENERATOR TUBE INSPECTION	10/31/78C	Insp. completed; deleted 3.E by NRC SER 10/31/78		
M08174	B-14	CEA GUIDE TUBE WEAR	07/10/80C	No action required; completed with NRC review		NRC Letter 7/10/80
M12133	B-16	EMERGENCY PLANNING AND REVISIONS	04/01/81C	Completed with NRC audit		NRC letter 5/9/83
M10815	B-17	TECH SPEC SURVEILLANCE FOR HYDRAULIC SNUBBERS	09/08/82C	T.S. issued NRC letter 10/15/84; remove exemption for testing large bore snubbers		
M10289	B-20	CONTAINMENT LEAKAGE DUE TO SEAL DETERIORATION	03/25/81C	Completed with approval of SCE letter 1/26/83		NRC letter 02/17/84
M10351	B-21	LOSS OF 125-V DC BUS VOLTAGE W/LOSS OF ANNUNCIATOR	04/29/81C			
M10152	B-22	TECH SPEC SURVEILLANCE REQUIREMENTS FOR MECHANICAL	09/08/82C	Completed with issuance of T.S.		NRC letter 10/15/84
M10051	B-23	DEGRADED GRID VOLTAGE	06/23/82C	Modifications to be implemented in accordance with ILS		
M42615	B-24	VENTING AND PURGING CONTAINMENTS WHILE AT FULL POWER	02/17/84C	Vent line use under NRC Review		SCE letter 1/21/86
M10189	B-24	VENTING AND PURGING CONTAINMENTS WHILE AT FULL POWER	03/15/81C	Completed with issuance of T.S.		NRC letter 02/17/84
M10245	B-26	INADVERTANT SAFETY INJECTION DURING COOL DOWN	09/14/79C			
M49431	B-32	BLOCKED SI SIGNAL DURING COOL DOWN	02/08/83C	Completed by NRC acceptance of config.		NRC letter 12/6/82
M08046	B-37	STEAM GENERATOR TUBE DENTING AND SUPPORT PLATE MOD	10/31/78C	Completed with issuance of T.S.		NRC SER 10/31/78
M08693	B-39	PWR PRESSURE - TEMPERATURE LIMIT TECH SPECS	11/13/80C	Completed with T.S. issuance		NRC SER 5/21/86
M11114	B-41	FIRE PROTECTION - (INCLUDES SER S	02/04/81C	Mods to be completed by RTS		6/86
M48143	B-41	FIRE PROTECTION - (INCLUDES SER S	11/18/82C	Superseded by NRC SER 5/15/86		
M47498	B-41	FIRE PROTECTION - (INCLUDES SER S	03/05/82C	Determined emergency lights not needed		NRC SER 5/15/86
M11696	B-42	TMI FOLLOW UP - ALL PLANTS	06/19/81C	No SCE action required		
M11825	B-43	PWR FEEDWATER LINE CRACKS	02/26/80C	Cracks repaired and inspected; completed with NRC approval		NRC letter 02/26/80

REGULATORY INFORMATION TRACKING SYSTEM

FACILITY IMPLEMENTATION

FACILITY: SAN ONOFRE 1 (CONTINUATION)

TAC NO.	MPA #	TITLE	LIC ACT COMPLETE	STATUS	LICENSEE	DATE
M43151	B-43	PWR FEEDWATER LINE CRACKS	05/25/82C	Completed		
M12439	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	NRC audit and review completed for 0578		NRC letter 5/2/80
M30570	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending		6/17/81
M30571	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending		6/17/81
M30572	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending		6/17/81; T.S. in effect 12/16/81
M30573	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed by station order issued		1/1/80
M30574	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed by station order issued		1/2/80
M30575	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Program implemented in outage ending		6/17/81
M30576	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending		6/17/81
M30577	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending		6/17/81
M30578	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending		6/17/81; NRC SER 4/18/83
M30579	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed study 1/17/80; completed mods in outage ending		6/17/81
M30580	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending		6/17/81
M30581	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending		6/17/81
M30582	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending		6/17/81
M30583	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Participated in WOG/EPRI program		1/80
M12920	B-45	WASH 1400 EVENT V, "PRIMARY COOLANT SYSTEM PRESSURE	03/03/81C	Completed with T.S. issuance		NRC order 4/20/81
M12582	B-46	ANALYSIS OF TURBINE DISC CRACKS	03/24/82C	Completed with SCE agreement to use inspection criteria		SCE letter 03/24/82
M48388	B-48	ADEQUACY OF STATION ELECTRIC DISTRIBUTION VOLTAGE	05/27/83C	Under NRC Review		SCE letter 12/4/85
M42131	B-57	DHR CAPABILITY	07/06/84	Completed by issuance of T.S.		10/4/84 T.S. Effective
M42916	B-59	MASONRY WALL DESIGN	11/07/85C	Analyses and tests performed; Completed with NRC approval		NRC SER 11/7/85

REGULATORY INFORMATION TRACKING SYSTEM

FACILITY IMPLEMENTATION

FACILITY: SAN ONOFRE 1 (CONTINUATION)

TAC NO.	MPA #	TITLE	LIC ACT COMPLETE	STATUS	LICENSEE	DATE
M42516	B-60	ENVIRONMENTAL QUALIFICATION	03/11/85C	To be completed by RTS		6/86
M42706	B-61	LOSS OF NON CLASS IE I&C POWER	07/22/82C			
M42777	B-62	ESF RESET CONTROL DESIGN DEFICIENCY	10/05/82C	Modifications to be implemented in accordance with ILS		
M43939	B-63	INTERIM PROCEDURES FOR SHORT TERM BLACKOUT	12/17/81C	Completed by emergency procedures		SCE letter 7/21/81
M47169	B-66	NATURAL CIRCULATION COOL DOWN	08/09/83C	WOG analysis completed 4/10/81; NRC concurs with SCE evaluation		NRC SER 8/9/83
M47549	B-67	THERMAL SHOCK	02/02/83C	Analysis completed		SCE letter 1/25/82
M47030	B-67	THERMAL SHOCK	01/21/82C	Analysis completed		SCE letter 11/4/81
M46861	B-69	IEB 80-4 MAINSTEAM LINE BREAK WITH CONTINUED FEEDW	09/27/82C	Completed evaluation; approved by		NRC SER 9/27/82
M49756	B-72	NUREG 0737 TECH SPECS (GENERIC LETTER 82-16)	11/02/84C	Completed with issuance of T.S.		NRC SER 11/2/84
M52797	B-76	ITEM 1.1 - POST TRIP REVIEW; PROGRAM DESCRIPTION &	05/09/85C	Completed with NRC approval of program		NRC SER 5/9/85
M52878	B-77	ITEM 2.1 - EQUIPMENT CLASSIFICATION & VENDOR INTER	09/30/86	Under NRC Review		SCE letter 11/28/83
M52959	B-78	ITEMS 3.1.1 & 3.1.2 - POST MAINTENANCE TEST PROCEDU	11/04/85C	Completed with NRC approval of testing		NRC SER 11/4/85
M53040	B-79	ITEM 3.1.3 - POST MAINTENANCE TESTING - CHANGES TO	08/19/85C	T.S. not required; completed with NRC approval		NRC SER 8/19/85
M53095	B-80	ITEM 4.1 - REACTOR TRIP SYSTEM RELIABILITY - VENDO	07/01/85C	Vendor mods implemented; completed by NRC approval		NRC SER 7/1/85
M53148	B-81	ITEMS 4.2.1 & 4.2.2 -PREVENTATIVE MAINT PROG FOR R	05/30/86	Under NRC Review		SCE letter 5/14/85
M53194	B-82	ITEM 4.3 - AUTOMATIC ACTUATION OF SHUNT TRIP ATTAC	09/24/84C	Provided original design; completed by NRC approval		NRC SER 11/28/84
M54566	B-83	TECH SPECIFICATIONS COVERED BY GENERIC LETTERS 83-	11/02/84C	T.S. being developed in accordance with WCAP 10271		
M53630	B-85	SALEM ATWS 1.2 DATA CAPABILITY	07/31/86	Additional information to be submitted 6/30/86		
M53713	B-86	SALEM ATWS 2.2 S-R COMPONENTS	01/31/84	Under NRC Review		SCE letter 7/2/85

REGULATORY INFORMATION TRACKING SYSTEM

FACILITY IMPLEMENTATION

FACILITY: SAN ONOFRE 1 (CONTINUATION)

TAC NO.	MPA #	TITLE	LIC ACT COMPLETE	STATUS	LICENSEE	DATE
M53796	B-87	SALEM ATWS 3.2.1 & 3.2.2 S-R COMPONENTS	11/04/85C	Completed with NRC approval of information	NRC SER	11/4/85
M53879	B-88	SALEM ATWS 3.2.3 T.S. S-R COMPONENTS	08/19/85C	T.S. not required; completed by NRC approval	NRC SER	8/19/85
M53935	B-89	SALEM ATWS 4.2.3 & 4.2.4 LIFE COMPONENTS	12/31/86	Under NRC Review	SCE letter	4/27/84
M55376	B-90	SALEM ATWS 4.3 W AND B&W T.S.	11/28/84C	T.S. being developed to be included with B-83		
M54106	B-92	SALEM ATWS 4.5.1 DIVERSE TRIP FEATURES	11/04/85C	Deferred to be resolved with B-93	NRC letter	11/04/85
M54023	B-93	SALEM ATWS 4.5.2 & 4.5.3 TEST ALTERNATIVES	05/01/87	Under NRC Review	SCE letter	10/1/84
M06491	C-01	PWR SECONDARY WATER CHEMISTRY MONITORING REQUIREMENT	06/30/82C	Comp. with issuance of license condition	NRC SER	6/30/82
M10150	C-06	PUMP SUPPORT - LAMELLAR TEARING	02/25/82C	Based on NUREG-0577 under generic review by NRC contractor		
M10155	C-07	FUEL HANDLING ACCIDENT INSIDE CONTAINMENT	09/25/78C			
M08082	C-10	CONTROL OF HEAVY LOADS OVER SPENT FUEL POOL (PHASE	11/04/85C	Procedure mods completed 1/15/83	NRC SER	11/4/85
M43664	C-14	AUXILIARY FEEDWATER SEISMIC QUALIFICATION	04/05/82C	To be completed by RTS	6/86	
M52268	C-15	CONTROL OF HEAVY LOADS - PHASE II (FOLLOW UP OF MPA	06/28/85C	No SCE action required	NRC SER	6/28/85
M58086	C-16	UTILITY RESPONSES TO STAFF RECOMMENDATIONS CONCERN	12/11/85C	Completed by submittal of information	SCE letter	6/26/85
M13178	D-04	PWR REACTOR VESSEL CAVITY SEAL RING MISSILE POTENT	02/01/84C			
M10148	D-10	ASYMMETRIC LOCA LOADS	02/25/82C	GDC 4 revised; SCE to withdraw exemption request	SCE letter	9/20/85
M10072	D-11	FISSION GAS RELEASE	04/28/81C			
M12293	D-15	HIGH ENERGY LINE BREAK & CONSEQUENTIAL SYSTEM FAIL	02/18/81C	Completed with procedural modifications	SCE letter	10/5/79
M43053	D-17	DEFINITION OF OPERABLE	06/11/81C	Completed by issuance of T.S.	6/11/81	
M55900	D-19	DIESEL GENERATOR RELIABILITY TECH SPECS (GL 84-15)	01/07/86C	Under NRC Review	SCE letters	2/14/85;
12/19/85						
M44057	F-01	I.A.1.1 SHIFT TECHNICAL ADVISOR	01/15/82C	Completed with program implementation	1/1/81	

REGULATORY INFORMATION TRACKING SYSTEM

FACILITY IMPLEMENTATION

FACILITY: SAN ONOFRE 1 (CONTINUATION)

TAC NO.	MPA #	TITLE	LIC ACT COMPLETE	STATUS	LICENSEE	DATE
M44128	F-02	I.A.1.3 SHIFT MANNING	02/17/84C	Plans submitted 2/4/82; completed with implementation		11/1/82
M44199	F-03	I.A.2.1 UPGRADING OF RO AND SRO TRAINING	10/26/82C	Upgraded plans submitted; completed with NRC approval		NRC SER 10/26/82
M44270	F-04	I.C.1.2/3.A EMERGENCY OPERATING PROCEDURES GENERIC	06/07/84C	Completed upgrades		11/27/84
M44340	F-05	I.C.1.2/3.B PROCEDURES GENERATION PACKAGES (NUREG	9/30/86	Completed with submittal of package		SCE letter 4/12/85
M47253	F-06	I.C.5 FEEDBACK OF OPERATING EXPERIENCE	01/27/82C	Completed by station procedures issued		5/1/82
M47325	F-07	I.C.6 CORRECT PERFORMANCE OF OPERATING ACTIVITIES	02/04/82C	Completed with NRC audit		NRC letter 2/4/82
M51200	F-08	I.D.1.1 DETAILED CONTROL ROOM DESIGN REVIEW PROGRAM	09/31/86	Submittal scheduled for		5/1/87
M51280	F-09	I.D.2 SAFETY PARAMETER DISPLAY SYSTEM	06/01/87	Design Criteria scheduled for 1/9/87;		Plan for final upgrades 6/1/87
M44407	F-10	II.B.1 RCS HIGH POINT VENTS	08/29/83C	Completed mods in outage ending		11/27/84
M47976	F-11	II.B.2 PLANT SHIELDING	04/18/83C	Completed mods in outage ending		11/27/84; NRC SER 4/18/83
M44478	F-12	II.B.3 POST ACCIDENT SAMPLING	11/07//85C	To be completed by RTS		6/86
M44549	F-13	II.B.4 TRAINING FOR MITIGATING CORE DAMAGE	10/26/82C	Completed training 2/10/82; Approved by NRC		NRC letter 10/26/82
M44620	F-14	II.D.1 RV AND SV TESTING	06/30/86	Under NRC review		SCE letters 12/2/82; 10/17/83; 10/1/85
M44652	F-15	II.E.1.1 AFW SYSTEM EVALUATION	10/22/82C	Completed with NRC approval and T.S. issuance		NRC SER 10/22/82
M44692	F-16	II.E.1.2.1 AFW SYSTEM INITIATION	11/18/82C	Final mods to be completed by RTS		6/86
M44731	F-17	II.E.1.2.2 AFW SYSTEM FLOW INDICATION	11/18/82C	Final mods to be completed by RTS		6/86
M44817	F-18	II.E.4.1 DEDICATED HYDROGEN PENETRATION	11/02/82C	Completed mods in outage ending		6/17/81
M44888	F-19	II.E.4.2 CONTAINMENT ISOLATION DEPENDABILITY	12/30/82C	Completed mods		8/6/81

REGULATORY INFORMATION TRACKING SYSTEM

FACILITY IMPLEMENTATION

FACILITY: SAN ONOFRE 1 (CONTINUATION)

TAC NO.	MPA #	TITLE	LIC ACT COMPLETE	STATUS	LICENSEE	DATE
M44959	F-20	II.F.1.1 NOBLE GAS MONITOR	01/29/82C	Completed mods		12/21/82
M45030	F-21	II.F.1.2 IODINE/PARTICULATE SAMPLING	05/13/82C	Completed mods in outage ending		11/27/84
M45101	F-22	II.F.1.3 CONTAINMENT HIGH RANGE MONITOR	02/24/82C	Completed mods in outage ending		11/27/84
M47637	F-23	II.F.1.4 CONTAINMENT PRESSURE INSTRUMENT	04/16/84C	Completed mods in outage ending		11/27/84
M47708	F-24	II.F.1.5 WATER LEVEL INSTRUMENT	04/16/84C	Completed mods in outage ending		11/27/84
M47779	F-25	II.F.1.6 CONTAINMENT HYDROGEN MONITOR	04/16/84C	Completed mods in outage ending		11/27/84
M45171	F-26	II.F.2 INSTRUMENTS FOR DETECTION ON INADEQUATE	01/31/88	ICC report submitted June 20, 1986		
M46906	F-30	II.K.2.13 THERMAL-MECHANICAL REPORT	06/13/84C	WOG analysis submitted; completed with NRC approval		NRC SER 6/13/84
M47819	F-33	II.K.2.17 POTENTIAL FOR VOIDING IN RCS	12/19/83C	WOG analysis submitted; completed with NRC approval		NRC SER 12/19/83
M45249	F-36	II.K.3.1 AUTO PORV ISOLATION	09/13/83C	WOG analysis submitted; completed with NRC approval		NRC SER 9/13/83
M45295	F-37	II.K.3.2 REPORT ON PORV FAILURES	09/13/83C	No action required; completed with NRC SER 9/13/83		
M45381	F-38	II.K.3.3 REPORTING SV AND RV FAILURES AND CHALLE	03/15/82C	Completed by procedures issued		2/5/81
M45412	F-39	II.K.3.5 AUTO TRIP OF RCPS	02/22/83C	Completed evaluation by SCE letter 10/10/85; mods to be scheduled in accordance with ILS		
M45461	F-40	II.K.3.9 PID CONTROLLER	01/04/82C	Completed mods in outage ending		6/17/81
M45491	F-41	II.K.3.10 ANTICIPATORY TRIP MODIFICATIONS	01/04/82C	Completed; no mods required		NRC letter 1/4/82
M45521	F-42	II.K.3.12 ANTICIPATORY TRIP ON TURBINE TRIP	01/04/82C	Completed; no mods required		SCE letter 6/13/80
M45667	F-47	II.K.3.17 ECCS OUTAGES	08/08/83C	Completed by report submitted		SCE letter 4/20/81
M48433	F-53	II.K.3.25 POWER ON PUMP SEALS	07/07/82C	Completed evaluation by SCE letter 1/11/82; NRC SER 7/7/82		
M45864	F-57	II.K.3.30 SB LOCA METHODS	5/30/85C	Completed with submittal of SBLOCA report	WOG letter 6/11/86	

REGULATORY INFORMATION TRACKING SYSTEM

R-1208731-001

FACILITY IMPLEMENTATION

FACILITY: SAN ONOFRE 1 (CONTINUATION)

TAC NO.	MPA #	TITLE	LIC ACT COMPLETE	STATUS	LICENSEE	DATE
M48203	F-58	II.K.3.31 COMPLIANCE WITH 10 CFR 50.46	12/31/86	Completed with submittal of SBLOCA report	WOG letter 6/11/86	
M45983	F-63	III.A.1.2 TECHNICAL SUPPORT CENTER	07/31/86	Completed mods		10/1/82
M46054	F-64	III.A.1.2 OPERATIONAL SUPPORT CENTER	07/31/86	Completed mods		10/1/82
M46126	F-65	III.A.1.2 EMERGENCY OPERATIONS FACILITY	07/31/86	Completed mods		10/1/82
M46198	F-66	III.A.1.2 NUCLEAR DATA LINK	07/30/82C	Not required		
M46270	F-67	III.A.1.2 EMERGENCY PLAN UPGRADE TO MEET RULE	05/09/83C	Completed with NRC audit		NRC letter 5/9/83
M46342	F-68	III.A.2.2 METEOROLOGICAL DATA UPGRADE	07/31/86	Under NRC review		SCE letter 12/16/85
M46413	F-69	III.D.3.3 IMPLANT RADIATION MONITORING	02/22/82C	Completed with mods and program during outage ending 6/17/81		
M46482	F-70	III.D.3.4 CONTROL ROOM HABITABILITY	02/03/84C	Under NRC Review		SCE letter 3/28/86
M56162	F-71	I.D.1.2 DETAILED CONTROL ROOM REVIEW (FOLLOWUP TO	08/01/87	See F-08		
M49685	G-01	REACTOR COOLANT PUMP TRIP (D660 - II.K.3.5)	05/01/84C	See F-39		

ACL:6876F