

**Comanche Peak Nuclear Power Plant, Units 3 & 4  
COL Application  
Part 2, FSAR**




Figure 2.5.2-214 Contribution to 10 Hz Rock Total Mean Hazard