

CRANE COLLAPSE – STATOR DROP Arkansas Nuclear One

Release In Entirety

DRP Counterpart Meeting Alfred Sanchez May 14, 2013

Agenda

- Background
- Event Description
- Site Priorities
- Resident Inspector Response
- Augmented Inspection Team
- Parting Thoughts
- Pictures

Background

- ANO Unit 1 Stator Replacement Project
- To Rewind (1R23) or Not to Rewind (1R24)
- Began Loading Crane in Turbine Building Late February 2013
- Construction Complete March 31, 2013
 - ----Animation Video here----

ANO Plant Status – March 31

<u>Unit 1</u>

- 1R24, Mode 6
- Green Risk
- RCS > 23' in Cavity
- Ready to Offload
- Ready for Green Train Maintenance Window
- A3/A4 Power
 Supplied via A1

Unit 2

- Mode 1, 100%
- Green Risk

Crane Collapse – Stator Drop March 31, 2013

- Structural Failure of Crane Support and Stator is Dropped
- Immediate Loss of Offsite Power to Unit 1
- Immediate Unit 2 Reactor Trip
- Breaker Explosion & Partial Loss of Offsite AC Power on Unit 2 (1.5 Hours After Trip)
- Notice of Unusual Event

Structural Failure of Crane

- Collapse Occurs with <u>NO WARNING!</u>
- Offsite Responders Notified (Fire and Ambulance)
- 1 Fatality and 8 Injured
- Emergency Response Organization Activated
- Loss of Blackout Diesel to Both Units
- Crushed and Severed 8" Fire Header
- 3 B.5.b Pumps and London Fire Truck in PA

Unit 1 Loss of Offsite Power

- A1/A2 Busses Located Directly Beneath Turbine Deck and Impact Area—A1 Locks Out/ A2 Bus was De-energized Previously
- Loss of Decay Heat Removal
- EDGs Function as Designed
- Loss of Instrument Air
- Loss of Spent Fuel Pool Cooling

Unit 2 Reactor Trip – Partial LOOP

- Trip of RCP B Breaker due to Vibration
- Reactor Protection System Trip
- Feeder Breaker Explosion and SU#3
 Lockout
- 2A1Bus Fast Transfer to SU#2
- 2A2 Bus De-energizes and EDG-2 Functions as Designed to load 2A4
- NOUE Declared for Explosion in PA

Unit 2 Reactor Trip – Partial LOOP


- Electrical Power Arrangement Results in Degraded Instrument Air Pressure
- Water Hammer In Feedwater Heaters
- Loss of Letdown, SDBCS, and Pressurizer Spray
- Natural Circulation Cool Down (First Time)

R

Licensee Priorities

UNIT 1

- Restore Offsite Power to Unit 1 Safety Busses from SU#1 Transformer via a Temporary Modification
 - SU#1 to Temporary Field Breaker to Blackout Diesel Electrical Feeder Lines
 - Required Complete De-energization of A3 Vital Bus...Only 1 EDG from Station Blackout
- Establish Temporary Modifications to Restore Non-Safety Related Power via Mobile Diesel Generators



Unit 1 (cont.)

- Reestablish Fire Suppression System
- Establish Redundant Offsite Power via Temporary Switchgear Powered by SU#2
- Defuel Unit 1 and Complete Portions of 1R24 in Reactor Building

R

Licensee Priorities

Unit 2


- Assess Physical Damage
- Repair & Replace Damaged Components
- Review Post Transient Report
- Forced Outage List
- Re-Start Checklist Items (On-Line April 28)
- Plant Start-Up Monitoring Plans

Resident Inspector Response

- Responded to the Site in Approx 1 Hour
- Control Room is Small & Very Crowded
- Ongoing Events in Control Room Made it Difficult to Break Away to Call Region
- Understanding Roles
- "Eyes-In-The-Field"
- Follow-Up Inspection (Temporary Modifications and Unit 2 Start-up)

Augmented Inspection Team

- Onsite Week of April 8th
- 10 Unresolved Items
- Most Significant Items
 - Risk Assessment for Stator Move
 - Evaluation of Vendor Engineering Products
 - Timeliness of Securing Temporary Fire Pump (SU#3 Transformer Lockout and Flooding)



Bradley, Dan

۲

From: Sent: To: Subject: Attachments: Miller, Geoffrey Monday, May 13, 2013 8:49 AM Bradley, Dan RE: Reminder to send the AIT slides AIT_pres_ANO.ppt

Dan,

Attached is the slide show we used at the meeting. Please let me know if you need more info.

1

Thank you,

Geoff

- -

Release

Release


From: Bradley, Dan Sent: Monday, May 13, 2013 10:43 AM To: Miller, Geoffrey Subject: Reminder to send the AIT slides


Thank you, Dan

Dan Bradley Project Engineer - Division of Reactor Projects Branch E U.S. NRC Region IV <u>dan.bradley@nrc.gov</u> 817-200-1506





Release In Entirety





























Release

Bradley, Dan

From:	Lusk, Rustin
Sent:	Friday, May 10, 2013 12:23 PM
То:	Howell, Art; Lewis, Robert; Kennedy, Kriss; Scott, Michael; Blount, Tom; Clark, Jeff;
	Sanchez, Alfred; Schaup, William; Fairbanks, Abin; Allen, Don; Azua, Ray; Melfi, Jim;
	Bradley, Dan; Hatfield, Gloria; Dricks, Victor; Uselding, Lara; Kalyanam, Kaly; Kellar, Ray;
	Herrera, Marisa; Williams, Loretta; Fuller, Karla; Weil, Jenny; OEMAIL Resource;
	ROPreports Resource; Huyck, Doug; R4DRP_AA
Subject:	ANO 2013002 IR
Attachments:	ANO 2013002-RP-AS ML13130A329.pdf - Public ADAMS Document

Good Afternoon,

Please see the attached report. Thank you.

Respectfully,

Rustin "Russ" Lusk Division of Reactor Projects, Division Admin Assistant U.S. Nuclear Regulatory Commission, Region IV Phone: (817) 200-1184 Fax: (817) 200-1278



"Faith is being sure of what we do not see & certain of what we hope for." ***R.I.P. Rick "Rypper" Rypien***

R

Parting Thoughts

- Real (Human) Risk at Operating Nuclear Power
 Plants
- Just Because it is a Secondary System, Not Safety-Related, or Shutdown Doesn't Mean That There is No Risk!
- When Observing Heavy Lifts...<u>Always</u> Consider Failure of Lifting Rig and Ensure You Are Out of Harms Way
- Keep Detailed Notes w/ Dates & Times
- Verify Information

REZEASE IN ENTIPETY



NRC Augmented Inspection Team Exit Meeting Arkansas Nuclear One

Nuclear Regulatory Commission - Region IV Russellville, AR May 9, 2013



- Introduction
- Purpose of an AIT
- Event Description
- Inspection Results
- Licensee Comments
- NRC Closing Remarks
- Question and Answer

Augmented Inspection Team

Fact-finding inspection

3

- Identify issues for follow up inspection
- Identify generic safety concerns

A

March 31 Dropped Stator Event

- Unit 1 RFO Stator Replacement
- Structural Failure of Lifting Rig
- Loss of Offsite Power to Unit 1
- Unit 2 Reactor Trip
- Partial Power Loss/Breaker Failure on Unit 2
- Notice of Unusual Event

A

5

Inspection Results

 Reactor plant safety systems responded as designed

 Entergy took appropriate actions to recover plant equipment on Units 1 and 2 and has initiated an extensive root cause evaluation effort



Summary of Charter Items

Event Chronology

- Operator Response
 Control of Temporary Modification
- Equipment Impact

 Structural Impact to Units 1 and 2

Summary of Charter Items

- Plant Response to the Event

 Control of Steam Generator Nozzle Dams
 Main Feedwater Regulating Valve Maintenance
 Flood Barrier Effectiveness
- Compensatory Measures

 Compensatory Actions for Fire Suppression
- Event Classification and Reporting – Timeliness of Emergency Declaration




Summary of Charter Items

Heavy Lift Preparations Shutdown Reactor Equipment Risk Implementation of Material Control Procedure

• Status of Cause Evaluation Efforts – Review of Causes/Corrective Actions

Operating Experience





Contacting the NRC

- Report an emergency
 (301) 816-5100 (call collect)
- Report a safety concern
 - (800) 695-7403
 - Allegation@nrc.gov
- General information or questions
 - <u>www.nrc.gov;</u> Select "What We Do" for Public Affairs
 - Victor Dricks, (817) 200-1128

Electronic Distribution

- To receive a summary of this meeting and begin receiving other plant-specific e-mail distributions, subscribe to the Operating Reactor Correspondence electronic distribution via <u>http://www.nrc.gov/public-involve/listserver/plants-by-region.html</u>.
- To discontinue receiving electronic distribution, you may unsubscribe at any time by visiting the same web address above.

11