

**Meeting Agenda**  
**Category 2 Public Meeting with AP1000 Licensees**  
**to Discuss Topics Related to AP1000 Testing Strategies**  
**February 5, 2014**  
**8:00 a.m. – 3:00 p.m.**

**Bridge Line information: 1-800-988-9769, Passcode: 36859#**

<b>Time</b>	<b>Topic</b>	<b>Lead</b>
<b>***** Public Session *****</b>		
8:00 a.m.	Opening Remarks/Introductions	All
8:05 a.m.	Purpose	NRC
8:15 a.m.	AP1000 Testing Overview	SNC/SCE&G/WEC
8:45 a.m.	Opportunity for Public Comment *	NRC
9:00 a.m.	Adjourn <b>Public Session</b> of Meeting/Break	NRC
<b>***** Proprietary Session *****</b>		
9:15 a.m.	Configuration Control and Baseline Process	SNC/SCE&G/WEC
10:30 a.m.	Break	
10:45 a.m.	AP1000 Testing Strategy/Program	SNC/SCE&G/WEC
11:30 a.m.	Break for Lunch	
12:30 a.m.	Protection & Safety Monitoring System – Factory Acceptance Testing (PMS-FAT)	SNC/SCE&G/WEC
1:15 p.m.	Plant Control System - Factory Acceptance Testing (PCS-FAT)	SNC/SCE&G/WEC
2:00 p.m.	Break	
2:15 p.m.	Path Forward/Action Items (Open Discussion)	All
3:00 p.m.	Adjourn <b>Proprietary Session</b>	NRC

*\*The public will be given opportunities to comment at these points in the meeting.*