

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Moon Pak, M.D.
811 Oakwood Drive
Suite 201
Rochester, MI 48307-1361

REPORT NUMBER(S) 14-001

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-37786

4. LICENSE NUMBER(S)

21-32680-01

5. DATE(S) OF INSPECTION

April 8, 2014

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Deborah A. Piskura, Health Physicist		4/8/14
BRANCH CHIEF	Aaron T. McCraw, Chief, MIB		4/16/14

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Moon Pak, M.D.
811 Oakwood Drive
Suite 201
Rochester, MI 48307-1361

REPORT NUMBER(S) 14-001

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-37786

4. LICENSE NUMBER(S)

21-32680-01

5. DATE(S) OF INSPECTION

April 8, 2014

6. INSPECTION PROCEDURES USED

87130

7. INSPECTION FOCUS AREAS

03.01- 03.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)

02201

2. PRIORITY

5

3. LICENSEE CONTACT

Alton Garfield Smith, M.D., RSO

4. TELEPHONE NUMBER

(248) 656-0177

☒ Main Office Inspection

Next Inspection Date: April 2019

☐ Field Office Inspection

☐ Temporary Job Site Inspection

PROGRAM SCOPE

This was routine inspection of a small private practice physician's office authorized to use licensed material permitted by Sections 35.100 and 35.200. The clinic performed studies on Mondays, Tuesdays and occasionally Thursdays. The nuclear medicine department was staffed with one part-time technologist who performed approximately 15-20 cardiac procedures monthly. The licensee received unit doses for its imaging studies from a licensed radiopharmacy. The licensee retained the services of a consultant physicist who audited the radiation safety program quarterly (last 1/24/2014, with no findings).

This inspection consisted of interviews with licensee personnel, a review of select records, a tour of the nuclear medicine department, and independent measurements. The inspector observed licensee personnel perform dose calibrator QA tests, radiation surveys, security of byproduct material, and use of personnel monitoring. The inspector observed the licensee staff administer one pharmacological stress study.

No violations of NRC requirements were identified during this inspection.