



Central File
50-261

USNRC REG
ATLANTA, GA

Carolina Power & Light Company

January 4, 1980

CO JAN 7 AIO: 36

FILE: NG-3513(R)

SERIAL: NO-80-002

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, N.W.
Atlanta, GA 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2

DOCKET NO. 50-261

LICENSE NO. DPR-23

RESPONSE TO IE BULLETIN 79-28, MALFUNCTION OF LIMIT SWITCHES

Dear Mr. O'Reilly:

In response to IE Bulletin No. 79-28, there was an investigation of the Robinson Plant facilities. The investigation has determined that there are no NAMCO Model EA180 stem-mounted limit switches (SMLS) in use or to be installed at this plant. Therefore, we plan no further action at this time.

If further information is required, please contact me.

Yours very truly,

B. J. Furr

Vice President - Nuclear Operations

SHC:jmb*

cc: Mr. Norman C. Moseley